

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A1623003261/upa3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 5J U12337at Workshop m/s Soon Son

of _____

Insured: SMJ 34204

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 815k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 7 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: L7A85303Veh No: 5J U12337Yr Regn: 18/11/09Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Nissan Latio Sportc.c. 1498Colour: BlackA/C: Insured / Std / NI / NASp. Reading: 270054T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1FAAC1120010108Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Ni / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or RotallaFront 6Rear 6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. 6 mmL/Bal. 6 mmD.O.A. 27/03/23D.O.I. 29/3/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27 9500see until 17-11-2024 sel yrs. 7mks.nett @ 86976/4/22 4/5 @ 6800 in bond Vincent.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

) TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

TOTAL

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To motor claims

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG Building

S,pore 079120

Accident date: 27/03/2023

Date:29/03/2023

Estimate cost to repair vel: SJU 1233J (Nissan Latio) claims under vel: SMJ3420U.

not Aikent
den
1/6 \$ 6800
7 dgs.
29/3/23
Telepho Ntany

1pce tail gate	Nett	\$ 1,484.60	Badgao — 1314.70
2pcs tail gate dampers@ \$307.20	"	614.40	no X
1pce tail gate trim cover	"	280.00	Ref/cne —
1pce tail gate emblem	"	70.00	ner — 45.00
1pce tail gate into plate 'NISMO'	"	100.00	ner — 50.00
1pce tail gate windscreen over rubber moulding	"	120.00	ner — 86.40
1set tail gate windscreen tape from	"	60.00	ner — 40 s/n
1pce tail gate windscreen inner sealant	"	140.00	ner 40 s/n
1pce tail gate top lock	"	138.50	3rd —
1pce tail gate lower lock	"	40.00	no X
1pce tail gate centre holder	"	213.00	one —
2pce tail lamps@ \$ 355.10	"	710.20	not one sts? one —
1pce tail gate rubber	"	181.40	7w1 — 145.00
2pcs tail lamp inner panel@ \$280.90	"	561.80	no X
1pce rear panel	"	516.50	badgao — 485.00
1pce rear panel lower lock cover jornish	"	97.80	7w1 —
2pcs rear fenders trim cover@ \$517.30	"	1,034.60	Ref/cne — 336.1X2 = 672.20
1pce rear bumper	"	782.70	Dis — 645.10
1set rear bumper reverse sensor	"	180.00	shard s/n
2pcs rear bumper side holders@ \$48.20	"	96.40	ner —
1set 30 pcs rear bumper inner clips@ \$5	"	50.00	ner — 30 s/n
10pcs rear bumper lower spoiler clips@ \$5	"	50.00	NS X
1pce rear bumper inner sponge	"	59.20	7w1 —
2pcs rear bumper plate lamps@ \$86.70	"	173.40	no X
1pc Rear bumper lower spoiler		\$ 1012.20	cne/7w1 — 800

s/n
s/n

672.20

s/n

s/n

1set

page 1

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To motor claims

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG Building

S,pore 079120

Accident date: 27/03/2023

Date:29/03/2023

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate cost to repair vel: SJU 1233J (Nissan Latio) claims under vel: SMJ3420U.

2pcs rear bumper side brackets @\$48	nett	\$ 96.00	x NN	page 2
1pce rear spare tyer top cover	"	390.00		waput
1pce rear panel lower centre cover	"	72.00		cm
		\$ 8,232.50		
Less 10%		823.25		
		\$ 7,409.25		
1pce rear windscreen sun x sticker		205.00	11 x	
1pce rear windscreen wiper motor S/N		817.80	11 x	
1pce rear centre lock switch S/N		178.20	11 x	
1pce rear number plate with cover		100.00	304 60 S/N	
To rustproof		150.00	60	
To dismantle/renew tail gate		150.00	60	
To remove/refit rear top spoiler		100.00	11 x	
To check wiring		50.00	20	
To dismantle/renew reverse sensors		100.00	50	
To remove/refit rear interior to effect repair		100.00	80	
To dismantle/renew rear bumper spoiler		150.00	11 x	
To remove/refit rear windscreen		140.00	120	
To dismantle/renew accident portion		1,800.00	1100	
To spray paint		1,800.00	1100	
	Total:	\$13,250.25		

2-6301-30

102

2-5671-17

S.N-330

L-2590

2-5671-17

6872