



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

7P Ulu.
Xinyu

Vehicle No. SLB8663G

BMW 116D

WBA1V720X0V724452

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR ADJUSTMENT	
PARTS (LIST ITEMS)						
1	FRONT NUMBER PLATE GARNISH <i>Delnd</i>			98.00		✓
2	FRONT BUMPER <i>Delnd</i>			1136.00		✓
3	FRONT BUMPER SIDE HOLDER @94 <i>Ken</i>			188.00		x
4	FRONT BUMPER LOWER GRILLE <i>Ken</i>			218.00		x
5	FRONT BUMPER SPONGE <i>Delnd</i>			194.00		✓
6	FRONT BUMPER REINFORCEMENT <i>Ken</i>			745.00		x
7	FRONT BUMPER LOGO <i>Ken</i>			76.00		✓
8	FRONT BUMPER FOG LAMP COVER @148 <i>Ken</i>			296.00		x
9	FRONT GRILLE @212 <i>Delnd</i>			424.00		✓
10	FRONT GRILLE CHROME @112 <i>Delnd</i>			224.00		✓
11	HEADLAMP @2436 <i>Delnd</i> <i>LH</i>			4872.00		✓ <i>2436</i>
				8471.00		
		less	5%	423.55	5%	
				8047.45		
SPECIAL NETT ITEMS						
1	FRONT NUMBER PLATE <i>Best</i>			30.00		✓
2	FRONT NUMBER PLATE HOLDER <i>Delnd</i>			30.00		✓
3	FRONT BUMPER CLIPS <i>Ken</i>			50.00		✓ <i>30</i>
Total Parts				110.00		

4588
4358.60

90



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Vehicle No. SLB8663G

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
	LABOUR		
1	PANEL BEATING	500.00	300
2	SPRAY PAINTING	400.00	250
3	WIRING	100.00	30
4	TO PERFORM DIAGNOSTIC TEST	200.00	x.
	Labour Total :	1200.00	
	TOTAL (PARTS & LABOUR):	9357.45	

Adrian L
F/S 29/03/23.
03 Days.

total: 5028.60
L/S: AK.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AK.