

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

HSBC-2

Name : Firdaus Bin Sarkiman (91746520)

Accident Date : 20-Mar-23

Vehicle No : FE8337 (DOR24062022)

Vehicle Model : Suzuki / FU150

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Fairing assy (1 set) <i>CNE</i>	\$600 1,350.00 —
1	Fron fork assy <i>11</i>	\$ 950.00 X
1	Fork under bracket <i>11</i>	\$ 280.00 X
1	Front wheel rim <i>11</i>	\$ 480.00 X
1	Front rim shaft <i>11</i>	\$ 88.00 X
1	Front rim bearing <i>11</i>	\$ 90.00 X
1	Front brake disc <i>11</i>	\$ 285.00 X
1	Handle-bar <i>11</i>	\$ 380.00 X
1 <i>LH</i>	Handle-bar ends (1 set) <i>mis</i>	\$40 145.00 —
1 <i>LH</i>	Hand grip (1 set) <i>CN7</i>	\$60 95.00 —
1	Windshield <i>CN7</i>	\$180 380.00 —
1	Headlamp assy <i>CNE</i>	\$300 480.00 —
1	Lampstay <i>11</i>	\$ 385.00 X
1	Mirror (1 set) <i>bow / mis</i>	\$ 170.00 —
1 <i>LH</i>	Front signals (1 set) <i>CN7</i>	\$145 280.00 —
1	Clutch lever <i>CN7</i>	\$ 95.00 —
1	Main stand <i>11</i>	\$ 195.00 X
1	Front footrest <i>CN7</i>	\$80 220.00 —
1	Front footrest bracket <i>304</i>	\$185 450.00 —
1	Gear pedal <i>304</i>	\$115 175.00 —
1	Rear footrest <i>CN7</i>	\$80 195.00 —
1	Rear footrest bracket <i>11</i>	\$190 425.00 X
1	Rear handle <i>CN7</i>	\$205 245.00 —
1	Rear signals <i>CN7</i>	\$102 280.00 —
1	Rear cover (matt) <i>CN7</i>	\$180 255.00 —
		\$ 8,373.00
		Less 10%
		\$ 837.30
		\$ 7,535.70

not Authored
her

29/3/23

2/5 \$2200/

3 days

the other up

2727
102
2625

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Firdaus Bin Sarkiman (91746520)

Accident Date : 20-Mar-23

Vehicle No : FE8337 (DOR24062022)

Vehicle Model : Suzuki / FU150

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	Ref SCR	\$	38.00	10
2	Fork oils	u y	\$	30.00	X
2	Fork oil seals	u 1	\$	56.00	X
1	Steering cone (1 set)	u 1	\$	95.00	X
1	E.R.P. IU	u 1	\$	180.00	X
1	Sticker (1 set)	nu	\$	120.00	60
			\$	519.00	


S/No. Labour

1	To provide towing service (LOD) S\$50.00	\$	-	
2	To check wiring and reset headlamp focusing	\$	u 1 80.00	X
3	To repair body frame	\$	u 1 420.00	X
4	To provide labour	\$	480.00	20
		\$	980.00	

Grand Total

\$ 9,034.70

Singapore Dollars: Nine Thiusand Thirty-Four and Cents: Seventy only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: