

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2023)
Parts: M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLD7619G)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	1,637.00 FL	*1,637.00 FL
2	1		*REAR BOOT OUTER GARNISH	Cracked	482.00 FL	*482.00 FL
3	1		*REAR BOOT TOP LOCK	Dented / Jammed	256.00 FL	*256.00 FL
4	1		*REAR BOOT BOTTOM LOCK	Not Necessary	58.00 FL	*- FL
5	1		*REAR BOOT RUBBER	Not Necessary	177.00 FL	*- FL
6	1		*REAR BOOT MAZDA 5 WORDINGS	Necessary	36.30 FL	*36.30 FL
7	1		*REAR BOOT SKYACTIVE TECHNOLOGY WORDINGS	Necessary	80.00 FL	*80.00 FL
8	1		*REAR BOOT MAZDA LOGO	Scratched	36.00 FL	*36.00 FL
9	2		*REAR BOOT NUMBER PLATE LAMP -LH/RH	Not Necessary	114.00 FL	*- FL
10	2		*REAR BOOT LAMP -LH/RH	Cracked	818.00 FL	*818.00 FL
11	1		*REAR BOOT GLASS MOULDING	Necessary	105.00 FL	*105.00 FL
12	1		*REAR BUMPER WITH LOWER (BLACK)	Dented	961.00 FL	*961.00 FL
13	1		*REAR BUMPER SIDE HOLDER -LH/RH	N/S Bent / O/S Not Necessary	96.00 FL	*48.00 FL
14	10		*REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Repair	155.00 FL	*- FL
16	2		*TAIL LAMP ASSY-LH/RH	Not Necessary	1,202.00 FL	*- FL
17	1		*REAR PANEL	Repair	545.00 FL	*- FL
18	1		*REAR PANEL TOP GARNISH	Not Necessary	84.40 FL	*- FL
19	1		*REAR NUMBER PLATE WITH CASING	Scratched	45.00 FS	*40.00 FS
20	1		*REAR BUMPER SENSOR	Shorted	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,155.70	4,747.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,378.14	901.46
Total Parts (\$\$)	5,777.56	3,845.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS ,CUT /WELD REAR PANEL ,REMOVE,REPLACE ACCIDENT PARTS	New	1,000.00	550.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS (PEARL)	New	1,000.00	600.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE ,REFIX REAR GARNISH ,CARPET ,CUSHION AND RELATED PARTS	New	150.00	60.00
5	TO TUFF-KOTE	New	90.00	30.00
6	TO TRANSFER REAR BUMPER SENSOR	New	50.00	50.00
7	TO REMOVE ,REPAIR REAR EXHAUST PIPE	New	100.00	0.00
8	TO TRANSFER BOOT FITTINGS	New	80.00	60.00
			Gross Labour Cost (\$\$)	1,370.00
			2,520.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >