

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited  
10 Eunus Road 8  
#09-04A Singapore Post Centre  
Singapore 408600From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhammad Afiq Bin Mohamed Kamal

Date: 03 Apr 2023

**Preliminary Advice**

Vehicle No	: SLK3418J	Accident Date	: 24/03/2023
Make	: MAZDA 6	Policy No.	: MPC23P00023800
Assignment Date	: 29/03/2023	Excess	: S\$0.00
Date of Inspection	: 31/3/2023	Est. Duration of Repair	: 5
Inspection At	: ACCORD AUTO SERVICES PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,800.70
Revised Amount	:S\$	2,495.70
Check Items (Estimated)	:S\$	275.00
Total	:S\$	2,770.70

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	39,660.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,340.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Part by part repair

Please note that the preliminary advise amount (Revised &amp; Check items) stated are subject to consistency check, part prices and labour cost .