

(08/11/13) wsf

ASS. REC. BY: FormREF: CS/CS 2300 3273/Ry3

6793

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: SLK 34183at Workshop m/s Accura Auto SLof 1009, BUKA ROAD LN3 #01-80Insured: ICS

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 750

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 70K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLK 34183 Yr Regn: 2017 JonType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 6 SEDAN 2.5L S/P c.c. 2488Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 80196 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6GL1031H0106059Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NII / S/Rim / STD A/Rim orTyre Size: F: 225/45R19R: 7.BS / DUN / EXNOVA GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front RearR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 24/03/23 D.O.I. 31/03/23Survey held at Accura

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair LIA T - 30k

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC23P00023800	Date of Loss:	24/03/2023
Vehicle Reg. No.:	SLK3418J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SOR JIN JIANG		
Make/Model:	MAZDA 6, 2.5 SEDAN SP.6EAT SR LED (A)	Vehicle Reg. Date:	13/01/2017
Vehicle Colour:	GREY		
Engine No:	PY20849916	Chassis No:	JM6GL1031H0106059
Odometer:	79964 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Remarks:	REQUEST PROCESS PART BY PARTS REPAIR.NO USED PARTS AVAILABLE. AT BUKIT MERAH CONTACT PERSON 92740999.		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,580.70
Miscellaneous Items	60.00
Labour	1,160.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (S\$)	3,800.70
+ GST 8.00% (S\$)	304.06
Nett Amount (S\$)	4,104.76

This claim is handled by: LAI YEAN KUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Mar 2023)

Parts: 143 MAZDA 6 2.5 SEDAN SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Accord Auto Services Pte Ltd/SLK3418J/29/03/2023 09:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT LH FENDER <i>bt</i> ✓	0.00	0.00	*520.00 F
2	1		*FRONT LH FENDER SHIELD <i>MIS</i> ✓	0.00	0.00	*65.00 F
3	1		*FRONT LH FOGLAMP ?	0.00	0.00	*250.00 F
4	1		*FRONT LH FOGLAMP GARNISH <i>crn</i> ✓	0.00	0.00	*12.00 F
5	1		*FRONT LH FOGLAMP CHROME <i>crn</i> ✓	0.00	0.00	*80.00 F
6	1		*FRONT BUMPER <i>tan</i> ✓	0.00	0.00	*500.00 F
7	1		*FRONT BUMPER LH SIDE RETAINER <i>br</i> ✓	0.00	0.00	*10.00 F

F=Franchise part.

Sub Total (S\$)	1,437.00
+ Margin on L,N Items 10.00% (S\$)	143.70
Total Parts (S\$)	1,580.70

Accord Auto Services Pte Ltd/SLK3418J/29/03/2023 09:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 NECESSARY CLIPS *u/*

30 ~~60.00~~

Sub Total (\$\$)

60.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 Spray Painting to All Affected Areas

New

600 ~~1,000.00~~

Labour Items

2 Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area (*Front LH Door & LH Rocker Panel)

New

500 ~~1,000.00~~

3 Check Wiring System & Light

New

X 80.00

4 To Check & Adjust Front Wheel Alignment

New

60 ~~80.00~~

Gross Labour Cost (\$\$)

2,160.00

Accord Auto Services Pte Ltd/SLK3418J/29/03/2023 09:34. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Revised
4p 90010068
5 days
1/3 P/P
31/03/23 @ 1500
EXESS: TBA
Revert
Rating after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 679J

Vehicle Details

Vehicle No.: SLK3418J

Vehicle to be Exported: No

Intended Deregistration Date: 02 Apr 2023

Vehicle Make: MAZDA

Vehicle Model: MAZDA6 4-DOOR SEDAN 2.5L SP6EAT SR LED

Primary Colour: Grey

Manufacturing Year: 2016

Engine No.: PY20849916

Chassis No.: JM6GL1031H0106059

Maximum Power Output: 141.0 kW (189 bhp)

Open Market Value: \$26,055.00

Original Registration Date: 13 Jan 2017

First Registration Date: 13 Jan 2017

Transfer Count: 1

Actual ARF Paid: \$28,477.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 12 Jan 2027

PARF Rebate Amount: \$18,510.00

Intended COE Rebate Details

COE Expiry Date: 12 Jan 2027

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$56,000.00

COE Rebate Amount: \$21,150.00

Total Rebate Amount: \$39,660.00

Mazda 6 2.5A Sunroof

[Overview](#)[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)**CAR CHOICE**
SINGAPORE**The Best Buying Experience****Price****\$76,800****Depreciation** ?

\$15,270 /yr

[View models with similar depre](#)**Reg Date**

03-May-2017

(4yrs 1mth COE left)

Mileage

60,000 km (10.1k /yr)

Manufactured ?

2017

Road Tax ?

\$1,786 /yr

Transmission

Auto

Dereg Value ?

\$42,200 as of today (change)

OMV ?

\$26,289

COE ?

\$54,501

ARF ?

\$28,805

Engine Cap

2,488 cc

Power

141.0 kW (189 bhp)

Curb Weight ?

1,515 kg

No. of Owners ?

1