

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI23003281/SNY3E2**Date:** 09/05/2023**REFERENCE**

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MAA00067

**Claimant Vehicle No :** SHA6121U**Insured Vehicle No :** SLK7535C

Date of Loss: 28/03/2023

Nature of Claim: TP Claim No: M2302037

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SHA6121U**

Make &amp; Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR2F53388

Reg. Date: 05/12/2019 (Man. Year: 2019)

Chassis No: JTDKB3FU003089565

Colour: Blue

Odometer: 0 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

**CONDITION OF TYRES**

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,046.72	155.00	1,891.72	92.43
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,240.00	1,450.00	790.00	35.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,297.72</b>	<b>1,616.00</b>	<b>2,681.72</b>	<b>62.40</b>
<b>+ GST 8.00/8.00% (S\$)</b>	343.82	129.28	214.54	62.40
<b>Nett Amount (S\$)</b>	<b>4,641.54</b>	<b>1,745.28</b>	<b>2,896.26</b>	<b>62.40</b>

**INSPECTION**

Date of Assignment:	29/03/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	30/03/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA6121U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR ASSY RH	Repair	1,264.00 FL	*- FL
2	1		*REAR DOOR ASSY RH	Repair	1,258.30 FL	*- FL
3	1		*FRT DOOR COMFORT LOGO	Necessary	75.00 F	*75.00 F
4	1		*REAR DOOR APPS LOGO	Necessary	80.00 F	*80.00 F
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					2,677.30	155.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					630.58	0.00
Total Parts (\$\$)					2,046.72	155.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	700.00
2	SPRAYPAINT	New	1,000.00	750.00
3	TRANSFER DOOR PARTS	New	240.00	0.00
Gross Labour Cost (\$\$)			2,240.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >