



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: HO WINNIE			Ref: CS3/HSB23002209/Wvp3e2-1 Date: 02/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SHC 3185U	Veh. Inspected	SNG 9069R
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S3M04JU8	Excess (\$)	0.00
	Assign From	HO WINNIE	Assign Date	28/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV 1.5 DX	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JHMRU1810GX202390	Colour	SILVER
	Odometer	78254 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	24/02/2023	Inspection Date	31/03/2023
	Survey held at	51, Paya Ubi Industrial Park, Ubi Avenue 1		
	Repairer	TY AUTOCARE SERVICES		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	