



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	27/02/2023 15:20 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	24/02/2023 16:20 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE TOWARDS TUAS AFTER SLIP ROAD INTO CTE AYE LP 637 F
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNG9069R
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ANNA PEH PEI YAN
NRIC No	S7810303E
Email Address	peh_anna@hotmail.com
Mobile Phone No	(Phone) +65-97991829
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Hr-v
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1498

#### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5132723002

#### DRIVER

Name of Driver	ANNA PEH PEI YAN
NRIC No	S7810303E
Date Of Birth	16/04/1978



Occupation	Outdoor
Date Of Driving Pass	03/04/2006
Driving experience	16 YEARS AND 10 MONTHS
Gender	Female
Mobile Number	(Phone) +65-97991829
Alt. Phone Number	-
Email Address	peh_anna@hotmail.com
Address	APT BLK 613 WOODLANDS AVENUE 4
Address complement	#12-479
Postcode	730613
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO ACCIDENT STATEMENT ATTACHED.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	KIV

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC3185U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SNF73S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



Describe Circumstance of the Accident

I was travelling toward CTE (Amk) on 24 Feb 2023 around 1620 hrs. The traffic condition was slow.

I was station due to the traffic condition was moderate. Suddenly I was hit twice. The taxi (Vehicle No. SHC 385U) hit me from behind. After alight from my vehicle (SNG 9069R) I realise that it was another car (Vehicle No. SNF 73S) that hit the taxi.

I called for the police and ambulance. When the police and ambulance arrived, the police took down our particular contacts and the medi check on us. They ensure that we are ok before they left.

I also exchange contacts and took photos of our cars. After that we also left the accident scene.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)





















# Enquire Vehicle's Insurance Particulars

Enquire Vehicle's Insurance Particulars ( As At 24 Feb 2023 / 16:20:00 )

## Vehicle Insurance Details

Vehicle No.:

**SHC3185U**

Make Description/Model:

**HYUNDAI / AE IONIQ HEV 1.6 DCT**

Insurance Company Name:

**HSBC LIFE (SINGAPORE) PTE. LTD.**

Business Transaction Reference No.:

**20230228120208433337**

**Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).**

Save as PDF

OK →

Print





# Thank you

You have successfully logged out.

Your last login date and time was 28 Feb 2023, 12:01:40.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

## Session Transaction History

S/No.	Asset Type	Asset ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SHC3185U	18.19 Enquire Veh Owner Info (Others) by Law Firm	26.75	28 Feb 2023 / 12:02:08

**BETHLEHEM AUTOMOTIVE PTE LTD**

201809311G  
5035 ANG MO KIO INDUSTRIAL PARK  
# 01-371 SINGAPORE 568538

UEN :

Tel : 6483 0189 / 9030 6757

Fax : 6481 7780

Email : fanbethlehemauto@yahoo.com

No :

SNG 9069R

**CAR RENTAL AGREEMENT**

Date : 24.02.2023

HIRER'S PARTICULARS	
Name : PEH WAN SHIEN ANNA	License Issue Date : 03.04.2006
UEN/NRIC/Driving License No. : S 7810303 E	License Pass Date : 03.04.2006
Address : 613 WOODLANDS AVE. 4 #12-479 (S) 730612	PDVL Pass Date :
Mobile No. : 97991829	Driving Experience : 10 yrs
Date Of Birth : 16.04.1978	Email :

AUTHORISED DRIVER'S PARTICULARS	
Name :	License Issue Date :
UEN/NRIC/Driving License No. :	License Pass Date :
Address :	PDVL Pass Date :
Mobile No. :	Driving Experience :
Date Of Birth :	Email :

Vehicle Registration No. : SKS 9561 H	Make/Model/Color : MAZDA 3
Rental Period ( Days / Weeks / Months ) :	Rate : \$130
Rental Start Date : 24.02.2023	Rental End Date :
Contract Period : 10 days	Deposit :
Advance Payment : \$1300	Additional Charges : (If applicable)

Collision Damage Waiver :		Date / Time / Mileage Out :				Date / Time / Mileage On :			
		24.02.2023 1810 pm				06.03.2023 17.10 pm			
Fuel Indication Out :	Empty	1/8	1/4	3/8	1/2	5/8	3/4	7/8	FULL
Fuel Indication In :	Empty	1/8	1/4	3/8	1/2	5/8	3/4	7/8	FULL

I have read and understood the contractual obligation and I hereby agree to be bound by it .

\*\*\* Failure to fulfill contract obligation may result in forfeiture of deposit at owner's discretion \*\*\*

Please kindly transfer payment to UOB A/C : 3493345956 or PAYNOW to UEN NO. : 201809311G

Kindly revert with proof at payment once done . Thanks

Signature of Hirer  
Date & Time : 24/02/23

Signature of Owner  
Date & Time : 24.02.2023

# TY AUTOCARE SERVICES

Blk 5033 Ang Mo Kio Industrial Park 2 #01-271 Singapore 569536

Tel/Fax: 67548101

Company Reg No. : 53429459J

---

21 March 2023

To: Anna Peh Pei Yan  
Blk 613 Woodlands Ave 4  
#12-479  
Singapore 730613

## FINAL REPAIR BILL


**MOTOR VEHICLE NO. SNG 9069R (Honda HRV)**

Repair Cost for motor vehicle no. SNG 9069R as per the surveyor's  
report of Messrs Constant Appraiser Services dated 10 March 2023.

Lump sum

**\$14,250.00 NETT**

***SINGAPORE DOLLARS: FOURTEEN THOUSAND TWO HUNDRED FIFTY ONLY.***



# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Mobile: 9007 5234

Email: constant\_as@yahoo.com.sg

RCB No. 53138015K

## INVOICE

To: Anna Peh Pei Yan  
Blk 613 Woodlands Ave 4  
#12-479  
Singapore 730613

Date : 10/03/2023

Invoice No : IV23-03015/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of:  Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SNG 9069R (Inclusive Of Photographs And Transport Charges)  Our reference : CAS/23-03/015	\$1,024.00
Total	\$1,024.00

E. & O.E

**Constant Appraiser Services**



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Mobile: 9007 5234

Email: constant\_as@yahoo.com.sg

RCB No. 53138015K

## Automobile Inspection Report

To: Anna Peh Pei Yan  
Blk 613 Woodlands Ave 4  
#12-479  
Singapore 730613

Date : 10/03/2023

Reference No : CAS/23-03/015

### General Information

Registration No. : SNG 9069R  
Accident Date : 24/02/2023

### Particulars of Damaged Vehicle

Colour	: Silver	Make & Model	: Honda HRV
Engine Capacity	: 1496 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 078254	Engine No.	: L15B4532391
Chassis No.	: JHMRU1810GX202390	Steering	: In Order
Registration Date	: 02/08/2017	Brake	: In Order

### Tyre Condition

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	70%
L/H Front Tyre	215/60R16	DUNLOP	70%
R/H Rear Tyre	215/60R16	DUNLOP	70%
L/H Rear Tyre	215/60R16	DUNLOP	70%

### Inspection

Repairer : TY Autocare Services  
Blk 5033 Ang Mo Kio Industrial Park 2 #01-271 Singapore 569536

### Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$20,910.40  
Revised Amount : \$14,250.00  
Less Excess : -  
Nett Total : \$14,250.00

### Remarks

- (A) Survey was done on 27/02/2023
- (B) Re-survey was done on 01/03/2023
- (C) Re-survey after repair was done on 06/03/2023
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.



**Adjustment On Repair Costs And Replacement Of Parts:**

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<b><u>PARTS REPLACEMENT – LIST ITEMS</u></b>			
1	1pc	Tailgate	Dented/Buckled	1,287.60	1,287.60
2	1set	Tailgate glass moulding	Necessary	121.60	121.60
3	1pc	Tailgate outer garnish	Broken	481.90	481.90
4	1pc	Tailgate emblem 'H'	Necessary	58.80	58.80
5	1pc	Tailgate emblem 'HRV'	Necessary	86.90	86.90
6	1pc	Tailgate emblem 'I-Vtec'	Necessary	89.90	89.90
7	2pcs	Tailgate lamp @ \$510.60	Cracked/Broken	1,021.20	1,021.20
8	2pcs	Tailgate licence lamp @ \$42.00	Serviceable	84.40	-
9	1pc	Tailgate outer pull switch	Serviceable	191.60	-
10	1pc	Tailgate inner trim board	Deformed/Broken	582.60	582.60
11	1pc	Tailgate inner lock	Bent/Jammed	310.60	310.60
12	1pc	Tailgate inner pull pocket	Deformed	86.90	86.90
13	1pc	Tailgate weatherstrip	Distorted	211.40	211.40
14	2pcs	Tailgate hinge @ \$65.50	Repair	131.00	-
15	2pcs	Tailgate damper @ \$181.60	Serviceable	363.20	-
16	2pcs	Tailgate stopper @ \$18.20	Necessary	36.40	36.40
17	2pcs	Taillamp @ \$560.90	Cracked/Broken	1,121.80	1,121.80
18	2pcs	Taillamp filler panel @ \$261.90	Repair	523.80	-
19	1pc	Rear bumper	Dented/Broken	829.60	829.60
20	2pcs	Rear bumper reflector @ \$68.60	Cracked/Broken	137.20	137.20
21	2pcs	Rear bumper side @ \$241.20	Dented/Torn	482.40	482.40
22	2pcs	Rear bumper side retainer @ \$48.90	Necessary/Broken	97.80	97.80
23	1pc	Rear end panel	Dented/Buckled	759.10	759.10
24	1pc	Rear end panel garnish	Deformed	265.20	265.20
25	1pc	Rear exhaust silencer	Dented/Bent	547.60	547.60
26	1pc	Rear exhaust silencer heat shield	Dented/Warped	99.60	99.60
27	1pc	Rear floor board	Dented/Torn	495.90	495.90
28	1pc	Rear floor tool tray	Deformed/Broken	361.90	361.90
29	1pc	Rear floor panel	Dented/Buckled	965.80	965.80
30	1pc	Rear floor panel side member LH	Bent/Twisted	391.80	391.80
31	1pc	Rear floor panel undercover	Deformed/Broken	281.60	281.60
32	2pcs	Rear fender arch garnish @ \$261.90	Torn/Broken	523.80	523.80
33	2pcs	Rear fender inner trim board @ \$581.90	Deformed/Broken	1,163.80	1,163.80

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>			
34	1pc	Rear smart keyless antenna	Damaged	195.60	195.60
35	1pc	Rear smart keyless buzze	Broken	199.50	199.50
36	1pc	Rear side chassis member LH	Bent/Twisted	670.60	670.60
			Sub total	15,260.40	13,966.40
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
1	1set	Tailgate glass sealant	Necessary	100.00	80.00
2	1set	Tailgate glass foam tape	Necessary	65.00	45.00
3	1set	Tailgate top spoiler clip	Necessary	80.00	50.00
4	1set	Tailgate outer garnish clip	Necessary	80.00	50.00
5	1set	Rear bumper clip	Necessary	45.00	30.00
6	1set	Reverse sensor	Damaged	280.00	220.00
7	1pc	Reverse camera	Serviceable	550.00	-
			Part total	16,460.40	14,441.40
		<u>LABOUR &amp; MISC. CHARGES</u>			
1		To remove, refix tailgate glass		150.00	120.00
2		To transfer tailgate mechanism		150.00	80.00
3		To remove & refix rear exhaust silencer		100.00	70.00
4		To check rear electrical wiring		50.00	20.00
5		To remove, refix rear trim & garnish		100.00	80.00
6		To remove, refix rear seat & carpet		130.00	100.00
7		To remove, refix reverse sensor & camera		120.00	80.00
8		To respray undercoating		150.00	100.00
9		To respray painting & etc		1,500.00	1,200.00
10		Panel beating, remove & replacing above parts		2,000.00	1,500.00
			Grand total	20,910.40	17,791.40
Recommended cost of lump sum repair (To its pre-accident condition)					14,250.00

**Adjustment/Recommendations**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$14,250.00** on a contractual basis. Under normal circumstances, the repair period would be about **6 (Six)** working days.

Yours faithfully,

**Constant Appraiser Services**



Lim Yong Tian (Sebastian)  
Licensed Appraiser  
Adv. Dip. In Mechanical Engineering (AUS)  
MSAAA









