



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23003282/Avy3m4 Date: 18/05/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 1317A	Veh. Inspected	SKK 8988J	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/03/23/2062	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	29/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	BMW 520I	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WBAJA12020WW33744	Colour	BLACK	
Odometer	52297 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45R18	MICHELIN	6 mm	
L/H Front Tyre	245/45R18	MICHELIN	6 mm	
R/H Rear Tyre	245/45R18	MICHELIN	6 mm	
L/H Rear Tyre	245/45R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/03/2023	Inspection Date	03/04/2023	
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	