



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9556D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	SCRATCHED	599.68	599.68
1	FRONT LH BUMPER RETAINER	NOT NECESSARY	48.93	-
1	FRONT LH BUMPER SIDE SUPPORT BRACKET	NOT NECESSARY	38.83	-
1	FRONT BUMPER ENERGY ABSORBER	NOT NECESSARY	99.86	-
1	FRONT LH FENDER PANEL	TO REPAIR SEE LABOUR	659.50	-
1	FRONT LH FENDER LINER	NOT NECESSARY	185.12	-
1	FRONT LH BUMPER FOG LAMP COVER	NOT NECESSARY	178.55	-
1	FRONT LH HEADLAMP	SCRATCHED	1,808.60	1,808.60
1	FRONT LH WHEEL RIM COVER	NOT NECESSARY	265.50	-
	LESS 20% DISCOUNT		-776.91	-481.66
			3,107.66	1,926.62
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	55.00	30.00
1	SET FRONT BUMPER RIVET (SN)	NECESSARY	50.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	55.00	-
			160.00	60.00
<u>LABOUR</u>				
	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF FRONT LH FENDER PANEL.		800.00	200.00
	TO RUST PROOFING OF AFFECTED AREAS.	NOT NECESSARY	100.00	-
	TO READJUST AND REALIGN HEADLAMP AIM.		100.00	30.00
	TO DIAGNOSTIC, CHECK WIRING, LIGHTING SYSTEM AND CLEAR FAULT CODE.	NOT NECESSARY	180.00	-
	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO RESPRAY FRONT BUMPER COVER.		250.00	200.00
	TO RESPRAY FRONT FENDER PANEL.		250.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY FRONT BONNET.	NOT NECESSARY	250.00	-
			2,050.00	630.00
GRAND TOTAL			5,317.66	2,616.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS/SMR23003283/Rqy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.