



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23003283/Rqy3m4 Date: 18/05/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMB 8017K	Veh. Inspected	SHA 9556D
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/03/23/7021	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	29/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI I40 1.7	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHLB41UMHU097792	Colour	YELLOW
	Odometer	576694 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/60R16	TRIANGLE	6 mm
	L/H Front Tyre	205/60R16	TRIANGLE	6 mm
	R/H Rear Tyre	205/60R16	TRIANGLE	6 mm
	L/H Rear Tyre	205/60R16	TRIANGLE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	23/03/2023	Inspection Date	29/03/2023
	Survey held at	31 CORPORATION ROAD SINGAPORE 649806		
	Repairer	DING AUTOMOTIVE PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	