

(08/11/13) wef

ASS. REC. BY: Pam

REF:

CS/SMR23003283/Rqy3

8394

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHA 9556Dat Workshop m/s DINH AUTOMOTIVEof 31, CORPORATION RDInsured: SMR

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 28K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA9556D Yr Regn: 2016 / DCLType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI I40 1.7 c.c. 1685Colour: YELLOW A/C: Insured / Std / NI / NASp. Reading: 576694 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM4LB414MHU097792Gen. Cond: Good / Fail / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TRIANGLE

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 23/03/23D.O.I. 29/03/23Survey held at DINH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 6K

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

TO :

FAX NO:

ESTIMATE REPORT

1ST Quotation

29/03/2023 15:41

JOB-NO: 50114951

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA9556D

TRANS: AUTO

CHASSIS: KMHLB41UMHU097792

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU700975

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREAS	1.00	800.00	0.00	800.00		Y	<u>200</u>
2 TO RUST PROOFING OF AFFECTED AREAS	1.00	100.00	0.00	100.00		Y	<u>X</u>
3 TO READJUST AND REALIGN HEADLAMP AIM	1.00	100.00	0.00	100.00		Y	<u>30</u>
4 TO DIAGNOSTIC, CHECK WIRING, LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	180.00	0.00	180.00		Y	<u>X</u>
5 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	120.00	0.00	120.00		Y	<u>X</u>
6 TO RESPRAY FRONT BUMPER COVER	1.00	250.00	0.00	250.00		Y	<u>200</u>
7 TO RESPRAY FRONT FENDER PANEL	1.00	250.00	0.00	250.00		Y	<u>200</u>
8 TO RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00		Y	<u>X</u>
TOTAL:		2,050.00	0.00	2,050.00			
MATERIALS							
1 FRONT BUMPER <i>scr</i>	1.00	599.68	119.94	479.74	L	Y	
2 FRONT LH BUMPER RETAINER	1.00	48.93	9.79	39.14	L	Y	
3 FRONT LH BUMPER SIDE SUPPORT BRACKET	1.00	38.83	7.77	31.06	L	Y	
4 FRONT BUMPER ENERGY ABSORBER	1.00	99.86	19.97	79.89	L	Y	
5 FRONT LH FENDER PANEL <i>requir</i>	1.00	659.50	131.90	527.60	L	Y	
6 FRONT LH FENDER LINER	1.00	185.12	37.02	148.10	L	Y	
7 FRONT LH BUMPER FOG LAMP COVER	1.00	178.55	35.71	142.84	L	Y	
8 FRONT LH HEADLAMP <i>scr</i>	1.00	1,808.60	361.72	1,446.88	L	Y	
9 FRONT LH WHEEL RIM COVER	1.00	265.50	53.10	212.40	L	Y	
10 FRONT BUMPER CLIP SET	1.00	55.00	0.00	55.00	S	Y	<u>30</u>
11 FRONT BUMPER RIVET SET	1.00	50.00	0.00	50.00	S	Y	<u>30</u>
12 FRONT FENDER INNER SHIELD CLIP SET	1.00	55.00	0.00	55.00	S	Y	<u>X</u>
TOTAL:		4,044.57	776.92	3,267.65			
TOTAL PARTS & LABOUR :		6,094.57	776.92	5,317.65			

EXCESS/LOADING:\$ 0.00

No. Of Day: 3 daysRE-SURVEY: BEFORE AFTER PAINTINGPART-BY-PART OR LUMP SUM \$DATE OF SURVEY: 29 / 03 / 23 @ 1550*Paul - 4p 90010068*

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
SURVEYED BY: <u>Paul</u>							

CONTACT NO: 90010568 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL: _____ FAX: _____

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

839G

Vehicle Details

Vehicle No.:

SHA9556D

Vehicle to be Exported:

No

Intended Deregistration Date:

03 Apr 2023

Vehicle Make:

HYUNDAI

Vehicle Model:

I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Primary Colour:

Yellow

Manufacturing Year:

2016

Engine No.:

D4FDGU700975

Chassis No.:

KMHLB41UMHU097792

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$19,826.00

Original Registration Date:

22 Dec 2016

First Registration Date:

22 Dec 2016

Transfer Count:

0

Actual ARF Paid:

\$19,826.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

21 Dec 2024

PARF Rebate Amount:

\$12,886.00

Intended COE Rebate Details

COE Expiry Date:

21 Dec 2024

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$41,017.00

COE Rebate Amount:

\$8,793.00

Total Rebate Amount:

\$21,679.00