

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63865592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 28/03/2023

User ID : munsan

Section A - Accident Details

Registration Number	SHF299D
Case Reference Number	TAX/03/23/2066
Registration Date	14/12/17
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TIEN AH TEE
Type of Accident	Side Swipe
Accident Date and Time	28/3/23 12:03 PM
Accident Reported Date and Time	28/3/23 2:03 PM
Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24118037
Special Instruction to ARC, if any	REAR LEFT
Prepared Date and Time	28/3/23 3:23 PM
Chassis Number	
Allegae	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$0.00
Total Spray Cost	\$1,674.00	\$0.00
Total Spare Part Cost	\$5,665.81	\$0.00
Total Other Cost	\$1,060.00	\$0.00
TOTAL COST	\$9,751.81	\$0.00
Jump Sum Total	\$9,750.00	\$0.00
Number of Repair Days	10.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	28/03/2023 3:45 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised
LKK

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/03/2023

User ID : munsan

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		7586047900	MOULDING ASSY, BODY ROCKER PANEL , LH	1.00	\$649.10	25.00	\$486.83	Replace	pn x
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	25.00	\$707.33	Replace	Ry ~
		6563847060	LINER, REAR FENDER , LH	1.00	\$151.10	25.00	\$113.32	Replace	pn x
		4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	pn ~
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	pn x
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR , REAR AXLE , RH & LH	1.00	\$644.10	10.00	\$579.69	Replace	?
			STICKER PETROL ONLY	1.00	\$7.80	0.00	\$7.80	Replace	pn x
Total					\$8,946.54		\$7,082.26		

Identified Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									