

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 16/04/2023

User ID : PohSuan

Section A - Accident Details

Registration Number	SHF299D
Case Reference Number	TAX/03/23/2066
Registration Date	14/Dec/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TIEN AH TEE
Type of Accident	Side Swipe
Accident Date and Time	28/Mar/2023 12:05 PM
Accident Reported Date and Time	28/Mar/2023 2:03 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118037
Special Instruction to ARC, if any	REAR LEFT
Prepared Date and Time	28/Mar/2023 3:23 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$700.00
Total Spray Cost	\$1,674.00	\$600.00
Total Spare Part Cost	\$5,665.81	\$2,960.30
Total Other Cost	\$1,060.00	\$270.00
TOTAL COST	\$9,751.81	\$4,530.30
Lump Sum Total	\$9,750.00	\$4,550.00 (L/S)
Number of Repair Days	10.0	6.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / Sompo
ARC / Surveyor Sign Off Date	29/03/2023 2:33 PM	29/03/2023 2:26 PM
Signature		
Remarks	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2304-0133	Invoice Number	
Quotation Date	16.04.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LH	\$1,352.00	\$700.00
Total Labour	\$1,352.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY DOOR HANDLE	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,674.00	\$600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$60.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE	\$120.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$50.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,060.00	\$270.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.18	Replace	Replace
		5246247020	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5246247030	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5246247010	PAD, RR BUMPER, RH & LH , 3	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given
		5259247040	SEAL, RR BUMPER , LH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/04/2023

User ID : PohSuan

		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√
		5245347010	GUARD, RR BUMPER, LOWER	0.00	\$623.50	0.00	\$0.00	Replace	Not Given	X
		5256647900	FILLER, RR BUMPER , LH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
		8156147151	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
		8159147010	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
		5839947030	COVER, REAR FLOOR UNDER , LH	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	X
		6700447210	PANEL SUB-ASSY, REAR DOOR , LH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Replace	√
		7586047900	MOULDING ASSY, BODY ROCKER PANEL , LH	0.00	\$649.10	0.00	\$0.00	Replace	Not Given	X
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	25.00	\$707.33	Replace	Replace	√
		6563847060	LINER, REAR FENDER , LH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X
		4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	Replace	√
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR , REAR	0.00	\$644.10	0.00	\$0.00	Replace	Check	X
			STICKER PETROL ONLY	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
Total					\$8,946.54		\$3,700.37			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	3,700.37	
	-20%	
	2960.30	L/S \$4,550/-
+	700.00	
+	870.00	
	4,530.30	