



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23003285/Uny3m4	
			Date: 06/04/2023	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMF 2203H	Veh. Inspected	SLE 7712P	
Policy No.	D22MTPV01019112	Coverage (\$)	0.00	
Claim No.	CMTD2301248/SYH	Excess (\$)	0.00	
Assign From	BETTY WONG	Assign Date	29/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS C HYBRID (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKD3B3101588426	Colour	SILVER	
Odometer	96082 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	185/60 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	7 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	28/03/2023	Inspection Date	29/03/2023	
Survey held at	XIN YUN AUTO PTE LTD BLK 8 KAKI BUKIT AVENUE 4 #05-23 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	