



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLE7712P TOYOTA PRIUS

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy D.S. —	791.10 \$ 1,206.00 —
2	1	Rear light right bracket CHA —	65.00 \$ 88.00 —
3	1	Rear bumper right bracket CHA —	\$ 98.00 —
4	1	Rear right fender air vent TWI. —	\$ 95.00 —
5	1	Rear bumper tow cover NIS X	\$ 80.00 X
6	1	Bumper lower cover AM X	\$ 150.00 X
7	1	Tailgate middle trim 11 X	\$ 358.30 X
8	1	Rear logo full set 11 X	\$ 200.00 X
9	1	Rear end top garnish 11 X	\$ 376.30 X
10	1	Rear tailgate RX	\$ 1,580.00 X
11	1	Tailgate inner trim cover 11 X	\$ 625.60 X
12	1	Rear tailgate weatherstrip 11 X	\$ 325.80 X
13	1	Rear tailgate lock mechanism 11 X	\$ 332.60 X
14	1	lock cover 11 X	\$ 95.00 X
15	1	Rear right wheel housing cover DIS —	\$96.20 120.00 —
16	2	Rear tailgate no plate lamp 11 X	\$ 170.00 X
17	1	Rear tailgate right taillamp CHA —	\$545 785.80 —
18	2	Rear tailgate damper 11 X	\$ 560.00 X
19	1	Reinforcement 11 X	\$561 685.30 —
20	2	Edge Molding / rear panel side Rear bumper brackets 11	\$ 300.00 —
21	1	Rear fender inner trim whole piece right RH TWI, 102	\$ 485.00 —
22	1	Keyless 11	\$ 450.00 X
23	1	Rear end panel Body 620.10	\$ 800.00 —
Parts Sub-total			\$ 9,966.70



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLE7712P TOYOTA PRIUS

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	1 set	Rear bumper clips 111	\$ 80.00 30
2	10	Rear end lower lip garnish clips 11	\$ 50.00 X
3	1	Rear end lower panel sealant 111	\$ 100.00 50
4	20	Rear tailgate inner trim board clips 11	\$ 80.00 X
5	10	Rear tailgate outer garnish clips 11	\$ 50.00 X
6	1 set	Rear fender inner trim clips 111	\$ 60.00 30
7	8	Tailgate middle trim clips 11	\$ 40.00
8	1	Rear windscreen glass sealant 11	\$ 80.00 X
9	1	Rear windscreen moulding 11	\$ 240.00 X
10	1	Rear no plate with garnish 11	\$ 80.00 X
11	1	Tyre RH 14T	\$ 200.00 60% 120
12	1	Reverse sensor with cable harness 111	\$ 600.00 200
13	1	Toyota rim 11	\$ 800.00 X
Special Nett Items			\$ 2,460.00

4/5 4500

Not Added
2/5 4500
7 days



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLE7712P TOYOTA PRIUS

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,800.00 1200
2	To putty and spray painting rear damaged portion.	\$ 1,800.00 1080
3	To check rear lighting and wiring.	\$ 60.00 20
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 111X
5	To remove & install rear windscreen glass to facilitate the repair.	\$ 150.00 111X
6	To apply anti rust proofing to rear affected area including behind	\$ 250.00 20
7	To remove and install rear end panel	\$ 120.00 X
8	To remove and install rear bumper reverse sensor.	\$ 80.00 50
9	To remove and install rear exhaust muffler assy.	11 \$ 120.00 X
10	To remove & install keyless, reset wirring to facilitate the repair.	\$ 120.00 X
11	To remove both internal fender trim facilitate the repair	\$ 120.00 80
12	To remove and install rear camera	\$ 80.00 111X
13	Water test	\$ 150.00 111X
14	To remove and trasnfer tailgate internal trim covers to facilitate	\$ 350.00 111X
15	To remove and replace tyre and rim	\$ 60.00 111X
16	To remove and install keyless system	\$ 60.00 111X
Total labour :		\$ 5,400.00

17826.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3657.4
252
2743.25
430
2460
5653.05
202
4522