



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23003288/Kvy3e2 Date: 18/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBS 6465D	Veh. Inspected	SJQ 6858U
Policy No.		Coverage (\$)	0.00
Claim No.	D23001090MFBP	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	29/03/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PICNIC (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTEGH23B200026546	Colour	METALLIC SILVER
Odometer	155956 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R18	CONTINENTAL	7 mm
L/H Front Tyre	225/45 R18	CONTINENTAL	7 mm
R/H Rear Tyre	225/45 R18	CONTINENTAL	7 mm
L/H Rear Tyre	225/45 R18	CONTINENTAL	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/03/2023	Inspection Date	30/03/2023
Survey held at	SIN MING AUTOCARE BFG PTE LTD 176, SIN MING DRIVE #02-05 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	