



HxGN EAM

Accident Report

User

NGTK@SBSTRANSIT.COM.SG

Report Created

May 5, 2023

Certificate of Bus Repair

Depot	UP	Bus No	SG6082L
Driver	79524	Accident Date	Jan 26, 2023
Work Order No	75009	Case No / AR No	11024 / AR-2023-0480

Date IN Feb 4, 2023

Date Out

Apr 13, 2023

Registration Date	Model/Manufacturer	Chassis No.
Mar 14, 2019	MNMQ	WMAA95ZZ3KF008735

Stock Code	Description	Quantity	Total Material Cost (\$\$)
30400878 N	VALVE COVER N	1	\$95.00
30117465 N	FRONT WINDSCREEN.LOWER.E6.FM SG6072 N	1	\$1,643.00
30400347 N	SIDE PANEL L6.E6 N	1	\$295.00
30400348 N	SIDE PANEL L9.E6 N	1	\$232.00
30400349 N	SIDE PANEL L10.E6 N	1	\$200.00
30400350 N	SIDE PANEL L11.E6 N	1	\$200.00
30400351 N	SIDE PANEL L12.E6 N	1	\$294.00
30400381 N	WHEELARCH TRIM.E6 N	3	\$300.00
30400442 N	ALUM STEP TRIM & RUBBER STRIP.EXIT DR N	1	\$37.50
30750229 N	ADHESIVE SIKA 265 600ML SAUSAGE N	30	\$401.80
43541069 N	BACK UP LIGHT ASSY.RR.A95.E6 N	1	\$97.45
30400541 N	WHEELCHAIR BUTTON W/INDICATOR.EXT.E6.A95 N	1	\$344.00
30400776 N	FRAME BOTTOM RUBBER(GV1240056).EXIT DR 3 N	1	\$550.00
30400777 N	FRAME BOTTOM RUBBER(GV1240055).EXIT DR 4 N	1	\$550.00

TOTAL FOR PARTS	\$\$	5,239.75
------------------------	-------------	-----------------

S/N	Labour / Spray Painting / Contractor Cost	Amount
1	Workshop Labour	S\$ 188.00
2	Contractor's Repair Charges	S\$ 2,600.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST		S\$ 2,788.00
Repair cost of Advertisement / Livery		S\$ 0.00
TOTAL DAMAGE		S\$ 8,027.75
Overheads		S\$ 2,408.33
Towing Charges		S\$ 0.00
Repair Period : 5.00 Days	Loss of Use	S\$ 2,106.55
TOTAL LOSS		S\$ 12,542.63