

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 6082L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	L/S FRONT WINDSCREEN	CRACKED	1,643.00	1,643.00
1	NS VIEW MIRROR	NOT NECESSARY	991.00	-
1	NS NO 2 BODY PANEL	SCRATCHED	295.00	295.00
1	NS NO 3 BODY PANEL	SCRATCHED	232.00	232.00
1	NS NO 4 BODY PANEL	SCRATCHED	200.00	200.00
1	NS NO 5 BODY PANEL	SCRATCHED	200.00	200.00
1	NS ENGINE FLAP PANEL	BENT	294.00	294.00
3	WHEELARC TRIM	CRACKED	300.00	300.00
2	EXT WAB PUSH BELL BUTTON	NOT NECESSARY	688.00	-
1	DOOR COCK VALVE COVER	CRACKED	95.00	95.00
1	ALUMINUM STEP TRIM	BENT	37.50	37.50
1	EXIT DOOR RUBBER (OS)	CUT	550.00	550.00
1	EXIT DOOR RUBBER (NS)	CUT	550.00	550.00
10	BOSTICK SEALANT WINDSCREEN	NOT NECESSARY	175.00	-
20	BOSTICK SEALANT PANEL	NOT NECESSARY	270.00	-
1	NS REVERSE LIGHT	NOT NECESSARY	94.00	-
1	ССТС	NOT NECESSARY	300.00	-
30	ADHESIVE SIKA 265 600ML SAUSAGE/N (ADDITIONAL)	NECESSARY	401.80	401.80
1	BACK UP LIGHT ASSY.RR.A95.E6/N (ADDITIONAL)	SCRATCHED	97.45	97.45
1	WHEELCHAIR BUTTON W/INDICATOR.EXT.E6.A95/N (ADDITIONAL)	SCRATCHED	344.00	344.00
			7,757.75	5,239.75
	<u>LABOUR</u>			
	TO REMOVE / REPLACE / REPAIR DAMAGED PARTS BY WORKSHOP.		188.00	188.00
	TO REMOVE / REPLACE / REPAIR DAMAGED PARTS BY CONTRACTOR.		2,600.00	2,600.00
	TO REMOVE / REPLACE / REPAIR DAMAGED ADVERTISEMENT PANEL (NPA).	NOT NECESSARY	-	-

Report Ref No. CS/LPC23003292/Rny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TOWING COST. (NPA)		-	-
			2,788.00	2,788.00
	GRAND TOTAL		10,545.75	8,027.75

RECOMMENDED COST OF REPAIRS	8,027.75
(REPAIR COST NOT CONCLUDE)	

Report Ref No. CS/LPC23003292/Rny3m4

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.2.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.