

Accident Repair Estimate

ACCIDENT DATE: 26-Jan-23 BUS NUMBER: SG6082L
 ACCIDENT TIME: 23:01 BUS MODEL: WDD
 ACCIDENT REPORT NUMBER: AR-2023-0480 DATE OF SURVEY: 30-Mar-23
 3RD PARTY CLAIM AGAINST: GBB6973T

SECTION A :

PARTS & MATERIAL COST

Part or Item Description	Quantity	Total Cost
30117465 L/S FRONT WINDSCREEN CR ✓	1	\$1,643.00 ✓
30400000 NS VIEW MIRROR X ✓	1	\$991.00 ✓
30400347 NS NO 2 BODY PANEL SC ✓	1	\$295.00 ✓
30400348 NS NO 3 BODY PANEL SC ✓	1	\$232.00 ✓
30400349 NS NO 4 BODY PANEL SC ✓	1	\$200.00 ✓
30400350 NS NO 4 BODY PANEL SC ✓	1	\$200.00 ✓
30400351 NS ENGINE FLAP PANEL SC ✓	1	\$294.00 ✓
30400381 WHEELARC TRIM CR ✓	3	\$300.00 ✓
30400541 EXT WAB PUSH BELL BUTTON CR X ✓	2	\$688.00 ✓
30400878 DOOR COCK VALVE COVER CR ✓	1	\$95.00 ✓
30400442 ALUMINUM STEP TRIM CR ✓	1	\$37.50 ✓
30400777 EXIT DOOR RUBBER (OS) CR ✓	1	\$550.00 ✓
30400776 EXIT DOOR RUBBER (NS) CR ✓	1	\$550.00 ✓
30730009 BOSTICK SEALANT WINDSCREEN X ✓	10	\$175.00 ✓
30122218 BOSTICK SEALANT PANEL CR X ✓	20	\$270.00 ✓
30400214 NS REVERSE LIGHT CR X ✓	1	\$94.00 ✓
SENSOR CCTC CR X ✓	1	\$300.00 ✓
TOTAL PARTS & MATERIAL COST		\$6,914.50

SECTION B:

ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)

To Remove / Replace / Repair Damaged Parts by Workshop	\$188.00
To Remove / Replace / Repair Damaged Parts by Contractor	2788 \$2,600.00
To Remove/ Replace/ Repair Damaged Advertisement Panel	\$0.00 X ✓
TOTAL LABOUR COST	\$2,788.00

SECTION C:

SUMMARY

Total Repair Costs	\$9,702.50
Total Downtime (Days)	5 \$2,106.55
Towing Cost	\$0.00
Total Overheads Costs	\$2,820.75
TOTAL COST	\$14,629.80

*Please kindly note that the downtime (days) is just an estimate.

*Please undersign to acknowledge this repair estimate.

Prepared by: JEFFREY LEONG
 Senior Foreman
 Ulu Pandan Workshop
 Bus Engineering

Surveyor Name & Contact: Rasul - Hp 90010068

Signature: [Signature] Signature: [Signature]

Date: 30/03/2023 Date: 30/03/23 @ 1520

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4396.50
 2788.00
 7184.50
 +supp 843.25
 8027.75
 4 days / P/P
 Res before paint
 15473.05

EAM

Accident Report

SBS Transit

Certificate of Bus Repair

Depot	UP	Bus No	SG6082L
Driver	79524	Accident Date	Jan 26, 2023
Work Order No	75009	Case No / AR No	11024 / AR-2023-0480

Date IN	Feb 4, 2023	Date Out	Apr 13, 2023
---------	-------------	----------	--------------

Registration Date	Model/Manufacturer	Chassis No.
Mar 14, 2019	MNMQ	WMAA95ZZ3KF008735

Stock Code	Description	Quantity	Total Material Cost (\$\$)
30400878 N	VALVE COVER N	1	\$95.00
30117465 N	FRONT WINDSCREEN.LOWER.E6.FM SG6072 N	1	\$1,643.00
30400347 N	SIDE PANEL L6.E6 N	1	\$295.00
30400348 N	SIDE PANEL L9.E6 N	1	\$232.00
30400349 N	SIDE PANEL L10.E6 N	1	\$200.00
30400350 N	SIDE PANEL L11.E6 N	1	\$200.00
30400351 N	SIDE PANEL L12.E6 N	1	\$294.00
30400381 N	WHEELARCH TRIM.E6 N	3	\$300.00
30400442 N	ALUM STEP TRIM & RUBBER STRIP.EXIT DR N	1	\$37.50
30750229 N	ADHESIVE SIKA 265 600ML SAUSAGE N <i>see</i>	30	\$401.80
43541069 N	BACK UP LIGHT ASSY.RR.A95.E6 N <i>see</i>	1	\$97.45
30400541 N	WHEELCHAIR BUTTON W/INDICATOR.EXT.E6.A95 N <i>see</i>	1	\$344.00
30400776 N	FRAME BOTTOM RUBBER(GV1240056).EXIT DR 3 N	1	\$550.00
30400777 N	FRAME BOTTOM RUBBER(GV1240055).EXIT DR 4 N	1	\$550.00

TOTAL FOR PARTS	\$\$	5,239.75
-----------------	------	----------