

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2303-205

DATE : 28-Mar-2023

POLICY NO. : BD P10858719R00

VEHICLE REG. NO. : SMJ4597L

VEHICLE MAKE : HYUNDAI ACCENT (RB) 1.4 CVT

TO Motor Claim Department
Allianz Global Corporate & Specialty SE
12 Marina View, Asia Square Tower 2
Singapore 018961
Tel: 6297 2529

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1	\$ 500.00	\$ 500.00
2	Front Bumper Clips	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH	1	\$ 50.00	\$ 50.00
4	Front Headlamp RH	1	\$ 800.00	\$ 800.00
5	Front Fender RH	1	\$ 620.00	\$ 620.00
6	Front Fender Shield RH	1	\$ 66.00	\$ 66.00
7	Front Fender Shield Clips	10	\$ 5.00	\$ 50.00
8	Front Bonnet Hinge RH	1	\$ 60.00	\$ 60.00
9	Front FogLamp RH	1	\$ 300.00	\$ 300.00
Total Spare Parts				\$ 2,496.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
10	Spray painting Front Bumper, Front Fender RH Including Blending	1	\$ 500.00	\$ 500.00
11	Remove, Replace, Repair and Refit Affected Area	1	\$ 500.00	\$ 500.00
12	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
13	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,130.00
Amount Before Excess				\$ 3,626.00
Add GST @ 7%				253.82
Total Amount Payable				\$ 3,879.82

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.