



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC23001660/Wwy3e2-1 Date: 03/05/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 8258R	Veh. Inspected	GBB 6973T
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/23/23/VC05/026973	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	29/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FB70	c.c	2977
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	FB70BBA20120	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	FALKEN	6 mm
	L/H Front Tyre	195 R15	FALKEN	6 mm
	R/H Rear Tyre	195 R15	FALKEN	6 mm
	L/H Rear Tyre	195 R15	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/02/2023	Inspection Date	15/02/2023
	Survey held at	KUO LI AUTO WORKSHOP BLK 5035 AMK INDUSTRIAL PARK 2 #01-363 SINGAPORE 569536		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	