

SQM PTE LTD

BLK 1003 , TOA PAYOH INDUSTRIAL PARK

05-1501 SINGAPORE 319075

EMAIL : SQM202088@GMAIL.COM . H.P 90030857 .

Date : 27 Mar 2023

QUOTATION - THIRD PARTY CLAIM

ALLIANZ INSURANCE SINGAPORE

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 3 Sep 2022

VEH. No : YN 8023 L / CANTER

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : SOMPO INSURANCE

Not Authorised
11 Png B
Penalty After Paim
6 days

QTY	ITEM	AMOUNT	CONDITION
Third party vehicle : GBE 5209 H			
1	FRONT W/SCREEN	\$ CM 1,895.00	✓
1	FRONT W/SCREEN RUBBER	\$ Na 323.00	50/100
1	FRONT WIPER PANEL GARNISH	\$ 685.00	7
1	FRONT WIPER ARM LH	\$ Na 332.00	✓
1	DASHBOARD	\$ Pa 1,985.60	X
1	FRONT CENTER PANEL	\$ Pa 1,224.50	✓
1	FUSO EMBLEM	\$ Na 240.00	✓
1	FRONT CORNER PANEL LH	\$ CM 526.00	✓
1	FRONT CORNER PANEL BRACKET LH	\$ K 180.00	X
1	SIDE MIRROR STAND LH	\$ Pa 480.00	✓
1	SIDE MIRROR TOP LH	\$ Mi's 336.00	✓
1	SIDE MIRROR (LOWER VIEW)	\$ Mi's 229.00	✓
1	HORN	\$ Pa 280.00	X
1	HORN OUTER PLATE	\$ K 85.00	X
1	FRONT GRILLE	\$ Mi's 520.00	✓
1	FRONT GRILLE EMBLEM	\$ Na 78.00	✓
2	HEADLAMPS	\$ Na CM 1,497.00	4
2	SIGNAL LAMPS	\$ CM 1,109.40	4
1	SIGNAL LAMP SIDE COVER LH	\$ Pa 296.00	X
1	FRONT DOOR LH	REPAIR	
1	STEP GARNISH LH	\$ Pa 424.00	X
1	FRONT BUMPER	\$ Pa 782.00	✓
1	FRONT BUMPER INNER BEAM	\$ 448.00	7
1	FRONT BUMPER SIDE	\$ Na/Na 298.00	✓
2	FRONT BUMPER BRACKETS	\$ Na/Na 181.50	4
1	CABIN SUPPORT SIDE BRACKET	\$ K 850.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL PARTS :

\$ 15,285.00

LESS 25%

\$ 3,821.25

TOTAL LIST PARTS :

\$ 11,463.75

<u>S/NETT PARTS</u>			
1	WIPER BLADE LH	\$ <i>Car</i> 220.00	✓
10	FRONT GRILLE CLIPS	\$ <i>re</i> 55.00	✓
2T	FRONT W/SCREEN SEALANT	\$ <i>re</i> 140.00	X
1	FRONT NO.PLATE	\$ <i>re</i> 50.00	X
S/NETT :		\$ 465.00	
TOTAL PARTS PRICE :		\$ 11,928.75	
AMOUNT BRING FORWARD :		\$ 11,928.75	

LABOUR CHARGES .

Labour charges to replace repair, align adjust on front accident affected area	\$ 1,400.00	<i>700l</i>
To replace remove refix front dashboard	\$ 500.00	<i>250l</i>
To replace front w/screen	\$ 250.00	<i>100l</i>
To remove refix garnish, trims, upholstery etc	\$ <i>re</i> 350.00	X
To do anti rust	\$ 120.00	<i>30l</i>
To do sealant seal gap, waterproofing on cutting welding accident affected area	\$ 200.00	<i>30l</i>
Check lamp wiring system, forcus headlamp	\$ 150.00	<i>20l</i>
To do spray painting on affected area inner outer	\$ 1,400.00	<i>700l</i>
TOTAL LABOUR :	\$ 4,370.00	
GRAND TOTAL PARTS & LABOUR :	\$ 16,298.75	