

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB23003300/KPA3Q2**Date:** 10/07/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_02  
**Claimant Vehicle No :** SGX5735X **Insured Vehicle No :** SKZ4568K  
 Date of Loss: 28/03/2023 Nature of Claim: TP Claim No: MFL2023D0003358

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SGX5735X**  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4675695  
 Reg. Date: 29/08/2007 (Man. Year: 2007) Chassis No: MR053ZEC107151098  
 Colour: Metallic Black Odometer: 166997 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

**CONDITION OF TYRES**

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14  
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm  
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>3,450.00</b>		
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>3,450.00</b>	<b>-3,450.00</b>	
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		26.75		
<b>Nett Liability (S\$)</b>		<b>3,776.75</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,770.00</b>		

**INSPECTION**

Date of Assignment: 29/03/2023  
 Date Inspected: 30/03/2023 Inspected At: Autoworx House - Sin Ming (HQ)  
 176 SIN MING DRIVE #02-01  
 Singapore 575721  
 Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGX5735X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
-----------------------------------------------

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >