

Not Authenth
Primary B4 pain

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHF591J

AAD2303-

Vehicle No.:
Chassis No.:
Co UEN.:
Vehicle Make:
Vehicle Model:
Date of Accident:
Third Party Insurer:
Date of Registration:

30 MAR 2023

SHF591J
JTDKB3FU203092709
200303878K
TOYOTA
PRIUS GEN 4
26/3/2023
SMP1101Y/ Allianz.
13/11/2020

PART

LIST

1	COVER, REAR BUMPER	\$	Bu	612.68	✓
1	COVER, REAR BUMPER, LOWER	\$	m	27.93	✓
1	GUARD, REAR BUMPER, CENTER	\$	B ₁	472.19	✓
1	SEAL, REAR BUMPER SIDE, LH	\$	B ₂	149.21	X
1	SEAL, REAR BUMPER SIDE, RH	\$	S ₂	149.21	X
1	RETAINER, REAR BUMPER SIDE, LH	\$	S ₂	167.48	X
1	REAR BUMPER SIDE RETAINER RH	\$	DT	167.48	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	B ₂	419.90	✓
1	REFLECTOR ASSY, REFLEX, LH	\$	S ₂	49.25	X
1	REFLECTOR ASSY, REFLEX, RH	\$	S ₂	49.25	X
1	COVER, FLOOR UNDER, RH	\$		220.50	7
1	COVER, FLOOR UNDER, LH	\$	S ₂	304.92	X
1	COVER, REAR FLOOR	\$		290.43	7
1	COVER, DECK TRIM, REAR	\$	S ₂	159.39	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	R	824.46	X
1	PANEL SUB-ASSY, BACK DOOR	\$	R	1,443.86	X
1	STAY ASSY, BACK DOOR, LH	\$	S ₂	305.66	X
1	STAY ASSY, BACK DOOR, RH	\$	S ₂	305.66	X
1	HINGE ASSY, BACK DOOR, LH	\$	R	77.18	X
1	HINGE ASSY, BACK DOOR, RH	\$	R	77.18	X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	mycm	1,156.89	✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	R	68.88	✓
1	PLATE, BACK DOOR NAME, NO.1	\$	R	68.88	✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	R	90.30	✓
1	BOX, DECK FLOOR, REAR	\$	S ₂	133.25	X
1	BOX, DECK FLOOR, RH	\$	S ₂	395.12	X
1	BOX, DECK FLOOR, LH	\$	S ₂	394.38	X
1	PANEL ASSY, DECK TRIM SIDE, LH	\$	S ₂	448.98	X
1	PANEL ASSY, DECK TRIM SIDE, RH	\$	S ₂	448.98	X

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
 SHF591J

AAD2303-

TOTAL	\$	4,064.28
25%	\$	1,016.07
	\$	3,048.21

SPECIAL NETT

1SET PARKING AID

1 REAR BUMPER CLIP

1 REAR SPOILER CLIP

1 REAR RH BUMPER RETAINER CLIP

1 REAR LH BUMPER RETAINER CLIP

1 REAR TAIL LAMP CLIP

1 END PANEL INNER TRIM CLIP

1 REAR BUMPER PROTECTOR

2 WINDSCREEN SEALANT

1 WINDSCREEN MOULDING

1 WINDSCREEN INNER SPONGE SEAL

1 Boot Sticker Transcab

1 Boot Sticker Tel. No

\$	700.00	22052
\$	65.00	6052
\$	65.00	X
\$	65.00	X
\$	65.00	X
\$	65.00	X
\$	60.00	X
\$	180.00	X
\$	150.00	X
\$	200.00	X
\$	130.00	X
TOTAL	\$	1,745.00
TOTAL PARTS	\$	4,793.21

LABOUR

To rust-proofing of the affected areas.

\$ 600.00 X

Putty and spray painting of the affected portion.

\$ 1,200.00 6601

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 4001

To transfer of tailgate fittings and conduct water seepage test.

\$ 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.

\$ 170.00 X

To transfer of tailgate fittings and conduct water seepage test.

\$ 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHF591J

AAD2303-

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *nn* 170.00 X

TOTAL \$ 5,420.00

OVERALL TOTAL \$ 10,213.21

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: