

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23003311/ANCE2**Date:** 03/08/2023**REFERENCE**

Insured/Claimant:	LIM SIM THONG (LIN SENTONG)	Policy No:	7220025234
Date of Loss:	22/03/2023	Nature of Claim:	OD Claim No: 2398611539SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE2372X	Engine No:	DEM033886
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF4XMA084028
Reg. Date:	25/02/2022 (Man. Year: 2021)	Odometer:	27851 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$182,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,608.00	5,726.40	3,881.60	40.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,732.00	1,452.00	2,280.00	61.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,340.00	7,178.40	6,161.60	46.19
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	12,240.00	6,078.40	6,161.60	50.34
+ GST 8.00/8.00% (S\$)	979.20	486.27	492.93	50.34
Nett Amount (S\$)	13,219.20	6,564.67	6,654.53	50.34

INSPECTION

Date of Assignment:	30/03/2023		
Date Inspected:	29/03/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	310.00 FS	*- FS
2	1		*FRONT NOISE INSULATION	Torn	683.00 FS	*546.00 FS
3	1		*REAR NOISE INSULATION	Torn	465.00 FS	*371.60 FS
4	2		*REAR UNDERBODY TRIM - LH / RH FRONT	Not Necessary	110.00 FS	*- FS
5	2		*FRONT UNDERBODY TRIM - LH / RH SIDE	Not Necessary	794.00 FS	*- FS
6	2		*REAR UNDERBODY TRIM - LH / RH SIDE	Not Necessary	328.00 FS	*- FS
7	1		*FUEL TANK TRIM	Not Necessary	72.00 FS	*- FS
8	1		*FUEL TANK	Punctured	5,971.00 FS	*4,776.80 FS
9	1		*SEAL RING	Necessary	40.00 FS	*32.00 FS
10	1		*HEAT SHIELD	Not Necessary	219.00 FS	*- FS
11	1		*TENSIONING STRAP - CENTER	Not Necessary	58.00 FS	*- FS
12	1		*TENSIONING STRAP - RH	Not Necessary	58.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	9,608.00 5,726.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO DISMANTLE AND REINSTALL FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	900.00	0.00
3	TO RESPRAY FRONT BUMPER	New	900.00	0.00
4	TO REMOVE AND REINSTALL REAR EXHAUST SILENCER ASSY TO FACILITATE RENEWAL OF FUEL TANK	New	480.00	480.00
5	TO REMOVE AND RENEW FUEL TANK ASSY	New	780.00	780.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,732.00	1,452.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >