

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0322/2023/EQ
DATE : 29-Mar-23
WIP : 13697

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM SIM THONG (LIN SENTONG)
ADDRESS : BLK 101 SERANGOON NORTH AVENUE 1
#13-821
SINGAPORE 550101
TELEPHONE : HP +65 92762959
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220025234
VEHICLE NO : **SNE 2372 X**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 25/2/2022
ENGINE NO : DEM 033886
CHASSIS NO : WAUZZZF4XMA084028
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Mar-23
PLACE OF ACCIDENT : SLIP ROAD ANG MO KIO AVE 3 EXOT AT CTE TOWARDS SLE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNE 2372 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	X
2	TO DISMANTLE AND REINSTALL FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	900.00	X
3	TO RESPRAY FRONT BUMPER.	\$	900.00	X
4	TO REMOVE AND REINSTALL REAR EXHAUST SILENCER ASSY TO FACILITATE RENEWAL OF FUEL TANK.	S/N \$	480.00	✓
5	TO REMOVE AND RENEW FUEL TANK ASSY.	S/N \$	780.00	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 3,732.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 2372 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 310.00	X
2	FRONT NOISE INSULATION <i>3 ton</i>	1	\$ 683.00	✓
3	REAR NOISE INSULATION	1	\$ 465.00	✓
4	FRONT UNDERBODY TRIM - LH / RH FRONT ?	2	\$ 110.00	?
5	FRONT UNDERBODY TRIM - LH / RH SIDE ?	2	\$ 794.00	?
6	REAR UNDERBODY TRIM - LH / RH SIDE ?	2	\$ 328.00	?
7	FUEL TANK TRIM ?	1	\$ 72.00	?
8	FUEL TANK <i>Punctured</i>	1	\$ 5,971.00	✓
9	SEAL RING <i>new</i>	1	\$ 40.00	✓
10	HEAT SHIELD <i>new</i>	1	\$ 219.00	X.
11	TENSIONING STRAP - CENTER <i>3 m</i>	1	\$ 58.00	✓
12	TENSIONING STRAP - RH	1	\$ 58.00	✓
13	SUNDRIES ?		\$ 500.00	?
TOTAL SPARE PARTS			\$ 9,608.00	
TOTAL LABOUR CHARGES			\$ 3,732.00	
GRAND TOTAL			\$ 13,340.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *29/03/23.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: