

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0303/2023/EQ
DATE : 24-Mar-23
WIP : 13260

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR NG SENG BOON
ADDRESS : 8 ANG MO KIO AVENUE 2
THE PANORAMA #16-06
SINGAPORE 567695
TELEPHONE : HP +65 92321223
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700027705-05
VEHICLE NO : **SLR 3368 H**
MODEL CODE : AUDI Q2 1.0 TFSI S-TRONIC
MODEL YEAR : 21/7/2017
ENGINE NO : CHZ 384673
CHASSIS NO : WAUZZZGA4HA058759
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Mar-23
PLACE OF ACCIDENT : MALAYSIA NORTH SOUTH HIGHWAY BETWEEN MACHAP
AND AIR HITAM

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLR 3368 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	500
4	TO RESPRAY FRONT BUMPER.	\$	1,000.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 3,152.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 3368 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	1	\$ 1,182.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 383.00	x
3	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 233.00	✓
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH ?	2	\$ 400.00	?
5	FRONT BUMPER END CAP - LH / RH ?	2	\$ 140.00	?
6	FRONT BUMPER SPOILER <i>Rehd</i>	1	\$ 352.00	✓
7	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 184.00	?
8	FRONT WHEEL SPOILER - LH <i>new</i>	1	\$ 41.00	x
9	FRONT BUMPER ADAPTER - LH <i>new</i> ?	1	\$ 43.00	?
10	RADIATOR GRILLE <i>new</i>	1	\$ 1,657.00	✓
11	RADIATOR GRILLE STRIKER PLATE <i>new</i>	1	\$ 146.00	x
12	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 92.00	x
13	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 813.00	x
14	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 43.00	x
15	FRONT BUMPER TOP COVER ?	1	\$ 119.00	?
16	CAUTION SIGN STICKER ?	1	\$ 17.00	?
17	AIR CONDITIONER STICKER ?	1	\$ 9.00	?
18	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 229.00	x
19	FRONT BUMPER AIR GUIDE - LH ?	1	\$ 47.00	?
20	FRONT BUMPER AIR GUIDE - UPPER CENTRE ?	1	\$ 47.00	?
SUB TOTAL SPARE PARTS		:	\$ 6,177.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 3368 H

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT BUMPER AIR GUIDE - RH <i>Not in</i>	1	\$ 47.00	X	
22	FRONT BUMPER AIR GUIDE SEAL - RH OUTER <i>Not in</i>	1	\$ 8.00	+	
23	FRONT WHEEL COVER - LH / RH <i>Not in</i>	2	\$ 762.00	✓	
24	FRONT NOISE INSULATION <i>Not in</i>	1	\$ 408.00	+	
25	HEADLIGHT MOUNTING - LH / RH <i>Not in</i>	2	\$ 280.00	X	
26	HEADLIGHT - LH <i>Not in</i>	1	\$ 5,550.00	X	
27	LIFT CYLINDER - LH / RH <i>Not in</i>	2	\$ 330.00	X	
28	LIFT CYLINDER HOSE <i>Not in</i>	1	\$ 208.00	+	
29	FRONT NUMBER PLATE <i>Not in</i>	S/N	\$ 60.00	✓	
30	SUNDRIES ?		\$ 400.00	✓	
TOTAL SPARE PARTS		:	\$ 14,230.00		
TOTAL LABOUR CHARGES		:	\$ 3,152.00		
GRAND TOTAL		:	\$ 17,382.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *29/03/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT