



樹發汽車修理廠
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065
Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	WSK/JW/SF-4584L
Policy No:	SP2004848774	Date of Loss:	29/03/2023
Vehicle Reg. No.:	SMQ4584L	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIEW MING HUA LUCAS	Contact No:	+6597991321
Driver:	LIEW MING HUA LUCAS		
Make/Model:	HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)	Vehicle Reg. Date:	16/03/2010
Vehicle Colour:	Silver		
Engine No:	G4FC9U798776	Chassis No:	KMH DU41BMAU963632
Odometer:	97296 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8.5		
Remarks:	VEHICLE IS IN.		
Present Location:	SHU FATT AUTO WORKS (HQ)		

COST OF CLAIMS	Amount
Parts	4,800.90
Miscellaneous Items	0.00
Labour	2,210.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	7,010.90
- Excess (S\$)	600.00
(S\$)	6,410.90
+ GST 8.00% (S\$)	512.87
Nett Amount (S\$)	6,923.77

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Mar 2023)

Parts: 143 HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Shu Fatt Auto Works/SMQ4584L/29/03/2023 17:07

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bonnet	0.00	0.00	*550.00 F _{BUC}
2	1		*Front bonnet insulator	0.00	0.00	*105.00 F _{NN}
3	12		*Front bonnet insulator clips	0.00	0.00	*30.00 F _{NEC}
4	1		*Front bonnet lock	0.00	0.00	*30.00 F _{BT}
5	2		*Front headlights	0.00	0.00	*600.00 F _{CPA}
6	2		*Front headlights holders	0.00	0.00	*50.00 F _?
7	1		*Front grille	0.00	0.00	*170.00 F _{CUT}
8	1		*Front grille emblem	0.00	0.00	*38.00 F _{NEC}
9	8		*Front grille clips	0.00	0.00	*20.00 F _{NEC}
10	2		*Front fenders	0.00	0.00	*360.00 F _{BUC}
11	2		*Front fenders cowlings	0.00	0.00	*100.00 F _{NN}
12	20		*Front fenders cowlings clips	0.00	0.00	*50.00 F _{NN}
13	1		*Front support panel	0.00	0.00	*480.00 F _{NN}
14	1		*Front bumper	0.00	0.00	*240.00 F _{CUT}
15	1		*Front bumper reinforcement	0.00	0.00	*120.00 F _{NN}
16	1		*Front bumper foam	0.00	0.00	*70.00 F _{NN}
17	2		*Front bumper brackets	0.00	0.00	*36.00 F _?
18	16		*Front bumper clips	0.00	0.00	*40.00 F _{NEC}
19	2		*Front bumper side retainers	0.00	0.00	*30.00 F _{NEC}
20	1		*Front bumper lower grille	0.00	0.00	*50.00 F _{NN}
21	8		*Front bumper lower grille clips	0.00	0.00	*20.00 F _{NN}
22	1		*Front bumper air con condenser	0.00	0.00	*550.00 F _{NN}
23	1		*Front aircon fan	0.00	0.00	*550.00 F _{NN}
24	1		*Front number plate	0	0.00	*55.00 FS _{BT}
25	1		*Coolant	0	0.00	*28.00 FS _{NN}

F=Franchise part. S=SpcNett.

Sub Total (S\$)	4,372.00
+ Margin on L,N Items 10.00% (S\$)	428.90
Total Parts (S\$)	4,800.90

Shu Fatt Auto Works/SMQ4584L/29/03/2023 17:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To knock frt inner panel, frt lower panel, frt side panel, left frt wheel house, right frt wheel house, frt lower member, renew frt bonnet, frt support panel, frt fenders, frt grille, frt lights, frt bumper & assembly.	New	600 900.00
2	To respray damaged parts.	New	800 1,050.00
3	to remove, replace aircon condenser and fill in aircon freon & compressor oil.	New	260.00 XHN
Gross Labour Cost (\$\$)			2,210.00

Shu Fatt Auto Works/SMQ4584L/29/03/2023 17:07. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 5 DAYS

- NOT AUTHORISE

- EXCESS \$600

- P/P OR I/S REPAIR?

- SURVEY BY EDWARD TEL: 62563561

- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

This claim is handled by: PATRICIA KOH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

> Back to OneMotoring

D.O.A.: 29/3/2023
97296km Bal.: 1 yr 9 mths.
M.V.: \$19,000.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	319E
Vehicle Details	
Vehicle No.:	SMQ4584L
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Apr 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U798776
Chassis No.:	KMH DU41BMAU963632
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,529.00
Original Registration Date:	16 Mar 2010
First Registration Date:	16 Mar 2010
Transfer Count:	①
Actual ARF Paid:	\$11,529.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited ✓
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2024 ✓
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$15,988.00
COE Rebate Amount:	\$5,552.00
Total Rebate Amount:	\$5,552.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Mar 2023

- Net value \$13,500.

OK

13,760
12,730
10,988
10,570