



樹發汽車修理廠
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065
Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	WSK/JW/SF-4584L
Policy No:	SP2004848774	Date of Loss:	29/03/2023
Vehicle Reg. No.:	SMQ4584L	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIEW MING HUA LUCAS	Contact No:	+6597991321
Driver:	LIEW MING HUA LUCAS		
Make/Model:	HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)	Vehicle Reg. Date:	16/03/2010
Vehicle Colour:	Silver		
Engine No:	G4FC9U798776	Chassis No:	KMH DU41BMAU963632
Odometer:	97296 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8.5		
Remarks:	VEHICLE IS IN.		
Present Location:	SHU FATT AUTO WORKS (HQ)		

COST OF CLAIMS	Amount
Parts	4,800.90
Miscellaneous Items	0.00
Labour	2,210.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	7,010.90
- Excess (S\$)	600.00
(S\$)	6,410.90
+ GST 8.00% (S\$)	512.87
Nett Amount (S\$)	6,923.77

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Mar 2023)

Parts: 143 HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Shu Fatt Auto Works/SMQ4584L/29/03/2023 17:07

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bonnet ✓	0.00	0.00	*550.00 F, BUC
2	1		*Front bonnet insulator X	0.00	0.00	*105.00 F, NN
3	12		*Front bonnet insulator clips ✓	0.00	0.00	*30.00 F, NEC
4	1		*Front bonnet lock X	0.00	0.00	*30.00 F, BT
5	2		*Front headlights ✓	0.00	0.00	*600.00 F, CPA
6	2		*Front headlights holders	0.00	0.00	*50.00 F, ?
7	1		*Front grille ✓	0.00	0.00	*170.00 F, CUT
8	1		*Front grille emblem ✓	0.00	0.00	*38.00 F, NEC
9	8		*Front grille clips	0.00	0.00	*20.00 F, NEC
10	2		*Front fenders bent (both) ✓ R L	0.00	0.00	*360.00 F, BUC
11	2		*Front fenders cowlings X	0.00	0.00	*100.00 F, NN
12	20		*Front fenders cowlings clips ✓	0.00	0.00	*50.00 F, NN
13	1		*Front support panel ✓	0.00	0.00	*480.00 F, NN ✓
14	1		*Front bumper ✓	0.00	0.00	*240.00 F, CUT
15	1		*Front bumper reinforcement bent ✓	0.00	0.00	*120.00 F, NN
16	1		*Front bumper foam ✓	0.00	0.00	*70.00 F, NN?
17	2		*Front bumper brackets ?	0.00	0.00	*36.00 F, ?
18	16		*Front bumper clips ✓	0.00	0.00	*40.00 F, NEC
19	2		*Front bumper side retainers ✓	0.00	0.00	*30.00 F, NEC
20	1		*Front bumper lower grille ✓	0.00	0.00	*50.00 F, NN
21	8		*Front bumper lower grille clips ?	0.00	0.00	*20.00 F, NN
22	1		*Front bumper air con condenser ?	0.00	0.00	*550.00 F, NN
23	1		*Front aircon fan ?	0.00	0.00	*550.00 F, NN
24	1		*Front number plate bent ✓	0	0.00	45 *55.00 FS, BT
25	1		*Coolant ?	0	0.00	*28.00 FS, NN

F=Franchise part S=SpcNett.

Sub Total (\$\$)	4,372.00
+ Margin on L,N Items 10.00% (\$\$)	428.90
Total Parts (\$\$)	4,800.90

Shu Fatt Auto Works/SMQ4584L/29/03/2023 17:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplementary

① L/50g lamp CA ✓

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To knock frt inner panel, frt lower panel, frt side panel, left frt wheel house, right frt wheel house, frt lower member, renew frt bonnet, frt support panel, frt fenders, frt grille, frt lights, frt bumper & assembly.	New	600 900.00
2	To respray damaged parts.	New	900 1,050.00
3	to remove, replace aircon condenser and fill in aircon freon & compressor oil.	New	260.00 XNN
Gross Labour Cost (\$\$)			2,210.00

Shu Fatt Auto Works/SMQ4584L/29/03/2023 17:07. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 6 DAYS

- NOT AUTHORISE
- EXCESS \$600
- P/P OR L/S REPAIR?
- SURVEY BY EDWARD TEL: 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: