

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0112/2023
DATE : 19-APR-2023

MINISTRY OF DEFENCE
HQ-TRANSPORT COMMAND
KRANJI CAMP3, 151 CHOA CHU KANG WAY
S(688248)
TEL : 62563561
FAX :

OWNER'S NAME : MR CHONG TECK WEI
ADDRESS : BLK 201, PETIR ROAD
#16-689
S(670201)
TELEPHONE NO : 97934137

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBF8459C
VEHICLE NO : SLM932A
MODEL CODE : DRLARDZC13UEAB-F-E
MODEL/YEAR : NISSAN PULSAR 1.2 MY2016
ENGINE NO : HRA2398983A
CHASSIS NO : VSKDDAC13U0098503
MILEAGE : 1 KM
DATE IN : 19/04/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 21/03/2023

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR IN WORKSHOP / CAR NOT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H / P : 94568832 FAX : 64697472

DIRECT SETTLEMENT

26/04/2023

10pm WED

(LAWRENCE)

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM932A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	/
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	/
3	WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	108.00	/
4	ZZ/001	REPAIR REAR BUMPER, RH REAR FENDER	900.00	580 585
5	ZZ/002	S/PAINT REAR BUMPER AND RH REAR FENDER	750.00	500
6	ZZ/003	RENEW RH REAR S/RIM AND CONDUCT WHEEL BALANCING	15.00	/
7	ZZ/004	RENEW RH REAR S/RIM TPS SENSOR	120.00	/
8	ZZ/005	RENEW RH REAR TYRE FALKEN FK510 205/50ZR17		
9	ZZ/006	R/I REVERSE SENSOR TO ASSIST REPAIR	55.00	/
TOTAL LABOUR CHARGES			2308.00	1743

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM932A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 GROMMET BUMPER \$3.00 EA X 02 <i>na</i> ✓	63846-5V000	6.00 ✓			
2 CLIP C/LAMP <i>na</i> ✓	26398-9N00A			7.30 ✓	
3 GROMMET RH COMB LAMP <i>? X na</i>	26557-2U000	5.40			
4 COMB LAMP RH <i>? X na</i>	26550-3ZL0A	514.60			
5 SUNDRIES <i>na</i> ✓	NPN			20.00 ✓	
6 205/50ZR17 FALKEN FK510 RH REAR <i>X na</i>	TYRE			250.00	
7 CLIP BUMPER \$1.50 EA X 04 <i>na</i> ✓	01553-10501	6.00 ✓			
8 BRKT REAR RH <i>? X na</i>	85226-3ZL0A	81.60			
9 SEN UNIT-TIRE P <i>? na photo</i> ✓	40700-4CB0B			178.90 ✓	
10 ALUMINIUM WHEEL RH REAR <i>na</i> ✓	D0300-3ZT3E			903.20 ✓	
SUB TOTAL		12 613.60	0.00	1359.40	1109.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		20% 122.72	0.00	0.00	
GRAND TOTAL		9.60 490.88	0.00	1359.40	1109.40
OVERALL TOTAL		1850.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLM932A

TOTAL LABOUR CHARGES	2308.00
TOTAL SPARE PARTS CHARGES	1850.28
GRAND TOTAL	4158.28 *

* All charges do2 not include GST.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR'S PARTICULARS

NAME	:	Rasmi - Hp 9000068
SURVEYED DATE	:	26/04/23 @ 1000
AUTHORIZED DATE	:	4 days
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	Revy after repair

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.