

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 932Aat Workshop m/s TAN CHONGof 93, PUKET TIMAH RDInsured: MINIB

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

100%Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 54K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lrm Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM 932A Yr Regn: 2012 MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NISSAN PULSAR 1.2 DIG-T c.c 1197Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 53484 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VS KODAC 1340098503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60ZR17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FAUKEN

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 21/03/23 D.O.I. 26/04/23Survey held at TAN CHONG

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S RGR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT-29K

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS SI

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0112/2023
DATE : 19-APR-2023

16372
19/04/2023

MINISTRY OF DEFENCE
HQ-TRANSPORT COMMAND
KRANJI CAMP3, 151 CHOA CHU KANG WAY
S(688248)
TEL : 62563561
FAX :

OWNER'S NAME : MR CHONG TECK WEI
ADDRESS : BLK 201, PETIR ROAD
#16-689
S(670201)
TELEPHONE NO : 97934137

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR IN WORKSHOP / CAR NOT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H / P : 94568832 FAX : 64697472

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBF8459C
VEHICLE NO : SLM932A
MODEL CODE : DRLARDZC13UEAB-F-E
MODEL/YEAR : NISSAN PULSAR 1.2 MY2016
ENGINE NO : HRA2398983A
CHASSIS NO : VSKDDAC13U0098503
MILEAGE : 1 KM
DATE IN : 19/04/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 21/03/2023

26/04/2023
13pm WBO
(Lawrence) ✓

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM932A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	/
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	/
3	WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	108.00	/
4	ZZ/001	REPAIR REAR BUMPER, RH REAR FENDER	900.00	580 585
5	ZZ/002	S/PAINT REAR BUMPER AND RH REAR FENDER	750.00	500
6	ZZ/003	RENEW RH REAR S/RIM AND CONDUCT WHEEL BALANCING	15.00	/
7	ZZ/004	RENEW RH REAR S/RIM TPS SENSOR	120.00	/
8	ZZ/005	RENEW RH REAR TYRE FALKEN FK510 205/50ZR17		
9	ZZ/006	R/I REVERSE SENSOR TO ASSIST REPAIR	55.00	/
TOTAL LABOUR CHARGES			2308.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM932A

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 GROMMET BUMPER \$3.00 EA X 02 <i>AM</i> /	63846-5V000	6.00		
2 CLIP C/LAMP <i>AM</i> /	26398-9N00A			7.30
3 GROMMET RH COMB LAMP ?	26557-2U000	5.40		
4 COMB LAMP RH ?	26550-3ZL0A	514.60		
5 SUNDRIES <i>AM</i> /	NPN			20.00
6 205/50ZR17 FALKEN FK510 RH REAR <i>X</i>	TYRE			250.00
7 CLIP BUMPER \$1.50 EA X 04 <i>AM</i> /	01553-10501	6.00		
8 BRKT REAR RH ? <i>X</i>	85226-3ZL0A	81.60		
9 SEN UNIT-TIRE P ? <i>see photo</i>	40700-4CB0B			178.90
10 ALUMINIUM WHEEL RH REAR <i>see</i> /	D0300-3ZT3E			903.20
SUB TOTAL		613.60	0.00	1359.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		122.72	0.00	0.00
GRAND TOTAL		490.88	0.00	1359.40
OVERALL TOTAL		1850.28		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLM932A

TOTAL LABOUR CHARGES	2308.00
TOTAL SPARE PARTS CHARGES	1850.28
GRAND TOTAL	4158.28 *

* All charges do2 not include GST.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

Rosme - Hp 90010068

26/04/23 @ 1000

4 days

Reay after repair

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	442I

Vehicle Details

Vehicle No.:	SLM932A
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Apr 2023
Vehicle Make:	NISSAN
Vehicle Model:	PULSAR 1.2L DIG-T
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	HRA2398983A
Chassis No.:	VSKDDAC13U0098503
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$17,541.00
Original Registration Date:	21 Mar 2017
First Registration Date:	21 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$7,541.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2027
PARF Rebate Amount:	\$4,901.00

Intended COE Rebate Details

COE Expiry Date:	20 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,789.00
COE Rebate Amount:	\$19,757.00
Total Rebate Amount:	\$24,658.00

The information contained herein is correct as at 27 Apr 2023

Nissan Pulsar 1.2A DIG-T

Overview

Financial

Insurance

Accessories

Similar

Research

Photos



Member of:



Accredited by:



Price	\$57,800		
Depreciation	\$13,310 /yr View models with similar depre	Reg Date	19-May-2017 (4yrs 21days COE left)
Mileage	77,100 km (13k /yr)	Manufactured	2017
Road Tax	\$508 /yr	Transmission	Auto
Dereg Value	\$26,023 as of today (change)	OMV	\$17,532
COE	\$51,106	ARF	\$7,532
Engine Cap	1,197 cc	Power	85.0 kW (113 bhp)
Curb Weight	1,265 kg	No. of Owners	2