Attn:

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd

> 6 Raffles Quay #22-00

Priya

Singapore 048580

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

(Estimate \$6.051.05 ±

18 Jul 2023 Date:

Preliminary Advice

Vehicle No : SLE7165T Accident Date : 05/03/2023 Policy No. : D18MFL0003414 Make : MAZDA BIANTE

Assignment Date : 30/03/2023 Excess : S\$0.00 Date of Inspection : 30/03/2023 Est. Duration of Repair : 5

: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) Inspection At

> 205 BRADDELL ROAD SINGAPORE 579701

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,087.29 (Estimate \$6,931.03 + Supplementary \$136.24)
Revised Amount	:S\$	4,004.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,004.10

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

Pre-Accident Value :S\$ 67,000.00 COE / PARF Rebate :S\$ 32,588.00

Salvage Value :S\$

Margin for Repair :S\$ 34,412.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: KINDLY APPROVE ON SUPPLEMENTARY.