



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA		Ref: CC4/HSB23003328/Upa3q2 Date: 16/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7135M	Veh. Inspected	JRB 2603
Policy No.	P2478220	Coverage (\$)	0.00
Claim No.	S3M04L1W	Excess (\$)	0.00
Assign From		Assign Date	30/03/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA INNOVA (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	PN111NV4018642640	Colour	SILVER
Odometer	121495 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R15	FRUN-ONE	6 mm
L/H Front Tyre	205/65 R15	FRUN-ONE	6 mm
R/H Rear Tyre	205/65 R15	FRUN-ONE	6 mm
L/H Rear Tyre	205/65 R15	FRUN-ONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/03/2023	Inspection Date	13/04/2023
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	