

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM 23003328/423

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

JRB2603

at Workshop m/s

off.

of

Insured:

SMC 7135M

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

RM 48k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: JRB2603

Yr Regn:

09/09/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make:

Toyota INNOVA

C.C

1998

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading:

121485

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65-R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Run-one

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

29/03/23

D.O.I.

13/4/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/04/23 1/5 & 5200 insured Alan

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

not Arthur  
13/4/23  
2/5 H 5200/  
3dys.

VEHICLE No: JRB 2603

|      |                                     |          |         |             |     |
|------|-------------------------------------|----------|---------|-------------|-----|
| 1PC  | REAR WINDSCREEN MOULDING            | 111      |         | \$188.30    | ✓   |
| 1PC  | TAILGATE                            | 3045.00  | 1845.00 | \$2,685.10  | ✓   |
| 1PC  | TAILGATE OUTER HANDLE               | 11       |         | \$344.80    | X   |
| 1PC  | TAILGATE REAR LOGO                  | 111      |         | \$68.50     | ✓   |
| 1PC  | TAILGATE 'INNOVA' EMBLEM            | 111      |         | \$96.80     | ✓   |
| 1PC  | TAILGATE '2.0' EMBLEM               | 111      |         | \$82.00     | ✓   |
| 1PC  | TAILGATE 'G' EMBLEM                 | 111      |         | \$60.00     | ✓   |
| 1PC  | TAILGATE WEATHERSTRIP               | 11       |         | \$488.90    | X   |
| 1PC  | TAILGATE INNER LOCK                 | Days     | 371.45  | \$641.90    | ✓   |
| 1PC  | TAILGATE INNER TRIM                 | 11       |         | \$811.60    | X   |
| 1PC  | REAR BUMPER                         | DD/70.1  | 1021.10 | \$1,715.10  | ✓   |
| 1PC  | REAR BUMPER LOWER SPOILER           | 11       | 1200.00 | \$1,500.00  | ✓   |
| 2PCS | REAR BUMPER REFLECTORS @\$85.00     | 11       |         | \$170.00    | X   |
| 2PCS | REAR BUMPER SIDE RETAINERS @\$65.00 | 111      |         | \$130.00    | ✓   |
| 2PCS | REAR BUMPER PDC SENSORS @\$285.00   | 8/10/11  |         | \$570.00    | 1PC |
| 1PC  | REAR END PANEL OUTER                | DD/10/11 | 681.10  | \$899.10    | ✓   |
| 1PC  | REAR END PANEL LOCK SENSOR          | 11       |         | \$350.00    | X   |
| 1PC  | REAR END PANEL TOP GARNISH          | 11       |         | \$468.90    | X   |
| 1PC  | TAILLAMP O/S                        | 11       |         | \$885.10    | X   |
| 1PC  | REAR FENDER                         | 11       |         | \$1,205.10  | X   |
| 1PC  | REAR EXHAUST                        | 11       | 252     | \$885.10    | X   |
| 1PC  | REAR EXHAUST CHROME                 | 11       |         | \$188.30    | X   |
|      |                                     |          |         | \$14,434.60 |     |

S.NETT

|      |                                    |     |          |    |
|------|------------------------------------|-----|----------|----|
| 1SET | REAR BUMPER CLIPS                  | 111 | \$50.00  | ✓  |
| 1PC  | REAR WINDSCREEN SEALANT            | 111 | \$50.00  | 40 |
| 1PC  | REAR WINDSCREEN INNER SEAL         | 111 | \$50.00  | 40 |
| 1PC  | REAR END PANEL SEALANT             | 111 | \$50.00  | ✓  |
| 1SET | TAILGATE INNER TRIM CLIPS          | 11  | \$50.00  | X  |
| 1SET | REAR FENDER INNER TRIM BOARD CLIPS | 11  | \$50.00  | X  |
| 1SET | REAR REVERSE CAMERA                | 11  | \$380.00 | X  |

TO CHECK WIRING

TO DISMANTLE & REPLACED REAR PDC SENSOR

TO DISMANTLE & REFIX REAR WINDSCREEN

TO DISMANTLE & REFIX CUSHION UPHOLSTERY

TO RESET & REPROGRAMME DIAGNOSIS SYSTEM

TO DISMANTLE & REFIX REAR EXHAUST

|    |          |     |
|----|----------|-----|
|    | \$50.00  | 20  |
|    | \$80.00  | 50  |
|    | \$150.00 | 120 |
|    | \$120.00 | 80  |
| 11 | \$100.00 | X   |
| 11 | \$100.00 | X   |



TO TRANSFER TAILGATE MECHANISM  
 TO SPRAY PROOFING  
 TO MOUNT VEHICLE ON CAR O-LINER  
 LABOUR FOR PANEL BEATING & REPLACED PARTS  
 TO PUTTY & SPRAY PAINTING

|       |             |     |
|-------|-------------|-----|
|       | \$100.00    | 80  |
|       | \$180.00    | 60  |
| 1^    | \$380.00    | X   |
|       | \$2,000.00  | 600 |
|       | \$2,000.00  | 800 |
| TOTAL | \$20,374.60 |     |

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

6029.25  
 252  
 4511.93  
 180  
 1870  
 6511.93  
 5209