

(08/11/13) wsf

ASS. REC. BY: Yam

REF:

CS/ALS 2800 3332/Rug3

396N

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: XE 7119Kat Workshop m/s SNH AH TEEof PUNBUL RD NORDH

Insured:

AMS

Policy No.

Claims No.

Sum Insured:

Excess:


2000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

200k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

XE 7119K

Yr Regn:

2022 / FEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ Truck / Trailer or

Make:

SCANIA P410A4X2M2c.c 12742

Colour

ORANGE

A/C:

Insured / Std / NI / NA

Sp. Reading

79279

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

452P4X20009296067Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

295/80R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

B

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

15/03/23

D.O.I.

30/03/23

Survey held at

SNH AH TEE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S & REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 177k

Date/Time, File Pass to?



: Prelim. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2004414441	Date of Loss:	15/03/2023
Vehicle Reg. No.:	XE7119K	Driveable?	
Driver Age/Info:	46 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WATERFRONT SERVICES PRIVATE LIMITED	Contact No:	+6590048489
Driver:	WANG HUACHENG		
Make/Model:	SCANIA P410A4X2NZ, 12.7 D (M)	Vehicle Reg. Date:	22/05/2022
Vehicle Colour:	MULTI-COLOUR		
Engine No:	DC13163L017337985	Chassis No:	YS2P4X20009296067
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	25		
Description of Accident/Loss	REFER TO SKETCH		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	63,360.80
Miscellaneous Items	0.00
Labour	7,450.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	70,810.80
+ GST 8.00% (S\$)	5,664.86
Nett Amount (S\$)	76,475.66

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

PAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Mar 2023)
 Parts: N/A SCANIA P410A4X2NZ 12.7 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for XE7119K)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>bt</i>	0.00	0.00	*4,700.00 F
2	1		*FRT BUMPER LEVER STEP <i>bt</i>	0.00	0.00	*1,500.00 F
3	1		*FRT BUMPER SIDE PIECE LH <i>bt</i>	0.00	0.00	*90.00 F
4	1		*FRT BUMPER STEP <i>X</i>	0.00	0.00	*700.00 F
5	1		*FRT BUMPER HOLDER TOP LH <i>?</i>	0.00	0.00	*185.00 F
6	1		*FRT LOWER GRILLE <i>X</i>	0.00	0.00	*385.00 F
7	1		*FRT LOWER GRILLE PROTECTOR LH <i>MIS</i>	0.00	0.00	*165.00 F
8	1		*FRT LOWER CTR PANEL <i>X</i>	0.00	0.00	*200.00 F
9	1		*FRT LOWER TOP <i>?</i>	0.00	0.00	*300.00 F
10	1		*FRT HEADLAMP LH <i>?</i>	0.00	0.00	*1,850.00 F
11	1		*FRT HEADLAMP NET <i>bt</i>	0.00	0.00	*350.00 F
12	1		*FRT HEADLAMP TOP GARNISH <i>X</i>	0.00	0.00	*200.00 F
13	1		*FRT HEADLAMP TOP SEAL <i>cut</i>	0.00	0.00	*40.00 F
14	1		*FRT HEADLAMP HINGE <i>?</i>	0.00	0.00	*40.00 F
15	1		*FRT HEADLAMP BRACKET <i>?</i>	0.00	0.00	*260.00 F
16	1		*FRT HEADLAMP TOP GARNISH COVER <i>?</i>	0.00	0.00	*30.00 F
17	1		*FRT HEADLAMP NET HINGE <i>?</i>	0.00	0.00	*50.00 F
18	1		*FRT HEADLAMP NET BRACKET <i>?</i>	0.00	0.00	*150.00 F
19	1		*FRT PANEL <i>con</i>	0.00	0.00	*1,650.00 F
20	1		*FRT PANEL FRAME <i>bt</i>	0.00	0.00	*300.00 F
21	1		*FRT PANEL BRACKET LH <i>?</i>	0.00	0.00	*150.00 F
22	1		*FRT PANEL LOWER GRILLE <i>de</i>	0.00	0.00	*225.00 F
23	1		*FRT PANEL SIDE GARNISH <i>MIS</i>	0.00	0.00	*920.00 F
24	1		*FRT PANEL SIDE GARNISH CLIP <i>rec</i>	0.00	0.00	*5.00 F
25	1		*FRT PANEL SIDE GARNISH STICKER <i>?</i>	0.00	0.00	*110.00 F
26	1		*FRT PANEL CTR GRILLE <i>con</i>	0.00	0.00	*275.00 F
27	1		*FRT PANEL SIDE GRILLE LH <i>de</i>	0.00	0.00	*260.00 F
28	1		*FRT PANEL TOP GARNISH <i>?</i>	0.00	0.00	*1,650.00 F
29	1		*FRT PANEL SCAN STICKER <i>rec</i>	0.00	0.00	*160.00 F
30	1		*FRT PANEL IA STICKER <i>rec</i>	0.00	0.00	*150.00 F
31	1		*FRT PANEL LIFTER LH <i>X</i>	0.00	0.00	*220.00 F
32	1		*FRT PANEL LOCK <i>bt</i>	0.00	0.00	*400.00 F
33	1		*FRT PANEL LOCK LATCH <i>bt</i>	0.00	0.00	*135.00 F
34	1		*FRT PANEL BOTTOM SEAL LH <i>rec</i>	0.00	0.00	*90.00 F
			TYPO: FRT PANEL BOTTOM SEAL LH			
35	1		*FRT PANEL LOCK STOPPER <i>rec</i>	0.00	0.00	*10.00 F
36	1		*FRT PANEL LOCK BRACKET LH <i>bt</i>	0.00	0.00	*120.00 F
37	1		*FRT PANEL TOP HANDLE LH <i>con</i>	0.00	0.00	*270.00 F
38	1		*FRT CORNER PANEL LH <i>bt</i>	0.00	0.00	*920.00 F
39	1		*FRT CORNER PANEL SEAL LH <i>rec</i>	0.00	0.00	*110.00 F
40	1		*FRT CORNER PANEL HINGE (TOP) <i>X</i>	0.00	0.00	*100.00 F
41	1		*FRT CORNER PANEL HINGE (BTM) <i>X</i>	0.00	0.00	*100.00 F
42	8		*FRT CORNER PANEL CLIP <i>rec</i>	0.00	0.00	*40.00 F
43	1		*FRT CORNER PANEL BRACKET LH <i>bt</i>	0.00	0.00	*120.00 F
44	1		*FRT WIPER GARNISH (CTR) <i>con</i>	0.00	0.00	*225.00 F

Qty	Part No.	Particulars	%Disc	%Depr	Amount
1		*FRT WIPER GARNISH BRACKET ?	0.00	0.00	*230.00 F
6	1	*FRT WIPER GARNISH LH <i>San</i>	0.00	0.00	*220.00 F
47	1	*FRT WIPER GARNISH HOLDER ?	0.00	0.00	*230.00 F
48	1	*FRT WINDSCREEN <i>cr</i>	0.00	0.00	*1,150.00 F
49	2	*FRT WINDSCREEN SEALANT <i>an</i>	0	0.00	*80.00 FS
50	1	*FRT SUNVISOR (TOP) <i>repair</i>	0.00	0.00	*450.00 F
51	1	*FRT SUNVISOR (BTM) <i>repair</i>	0.00	0.00	*440.00 F
52	1	*FRT SUNVISOR LAMP LH <i>cr</i>	0.00	0.00	*125.00 F
53	1	*FRT SUNVISOR MIRROR LH <i>br</i>	0.00	0.00	*390.00 F
54	1	*FRT CABIN ROLL BAR ?	0.00	0.00	*3,500.00 F
55	1	*FRT CABIN ROLL BAR STOPPER <i>stopper?</i>	0.00	0.00	*130.00 F
56	1	*FRT CABIN SUPPORT TOP <i>br</i>	0.00	0.00	*1,800.00 F
57	1	*FRT CABIN ROLL BAR BUSH ?	0.00	0.00	*225.00 F
58	1	*FRT CABIN ROLL BAR BRACKET (LH) ?	0.00	0.00	*780.00 F
59	1	*FRT CABIN ROLL BAR JOINT (LH) ?	0.00	0.00	*1,120.00 F
60	1	*FRT CABIN SHOCKABSORBER (LH) <i>br</i>	0.00	0.00	*700.00 F
61	1	*FRT CABIN SHOCKABSORBER LOCK (LH) ?	0.00	0.00	*195.00 F
62	1	*FRT CABIN SHOCKABSORBER TOP MOUNT ?	0.00	0.00	*290.00 F
63	1	*FRT CABIN SHOCKABSORBER LINK (LH) ?	0.00	0.00	*285.00 F
64	1	*FRT CABIN SHOCKABSORBER HOLDER ?	0.00	0.00	*185.00 F
65	1	*RADIATOR ?	0.00	0.00	*3,500.00 F
66	1	*RADIATOR NET <i>br</i>	0.00	0.00	*795.00 F
67	1	*INTERCOOLER ?	0.00	0.00	*3,330.00 F
68	1	*ENGINE OIL FILER CAP MIS	0.00	0.00	*78.00 F
69	1	*ENGINE OIL FILER NECK <i>de</i>	0.00	0.00	*245.00 F
70	1	*ENGINE OIL FILER BRACKET <i>br</i>	0.00	0.00	*315.00 F
71	1	*COOLANT TANK X	0.00	0.00	*450.00 F
72	1	*WIRE HARNESS BASE ?	0.00	0.00	*290.00 F
73	1	*WIRE HARNESS COVER ?	0.00	0.00	*220.00 F
74	1	*WIRE HARNESS METAL COVER ?	0.00	0.00	*350.00 F
75	1	*FRT STEP GARNISH (LH) ?	0.00	0.00	*445.00 F
76	1	*FRT WHEEL ARCH GARNISH (LH) ?	0.00	0.00	*1,150.00 F
77	1	*FRT WHEEL ARCH PROTECTOR (LH) ?	0.00	0.00	*455.00 F
78	1	*FRT DOOR (LH) <i>repair</i>	0.00	0.00	*4,995.00 F
79	1	*FRT DOOR SEAL (FRT) X	0.00	0.00	*75.00 F
80	1	*FRT DOOR HINGE (TOP) X	0.00	0.00	*380.00 F
81	1	*FRT DOOR HINGE (BOTTOM) X	0.00	0.00	*380.00 F
82	1	*FRT DOOR RUBBER X	0.00	0.00	*445.00 F
83	1	*FRT DOOR LOWER GARNISH (LH) X	0.00	0.00	*600.00 F
84	1	*RR CABIN SUPPORT (TOP) ?	0.00	0.00	*1,100.00 F
85	1	*RR CABIN SHOCKABSORBER ?	0.00	0.00	*725.00 F
86	1	*RR CABIN SHOCKABSORBER BRACKET (LH) ?	0.00	0.00	*180.00 F
87	1	*RR CABIN SIDE LIFTER (LH) ?	0.00	0.00	*420.00 F
88	1	*RR CABIN SIDE LIFTER BRACKET (LH) ?	0.00	0.00	*290.00 F
89	1	*RR CABIN SUPPORT (BOTTOM) ?	0.00	0.00	*980.00 F
90	1	*REAR TRAILER SOCKET BRACKET ?	0.00	0.00	*880.00 F
91	2	*REAR TRAILER SOCKET ?	0.00	0.00	*270.00 F
92	1	*REAR CABIN LOCK ?	0.00	0.00	*1,500.00 F
93	1	*INTERCOOLER MOUNTING ?	0.00	0.00	*330.00 F

F=Franchise part, S=SpcNett.

Sub Total (\$\$)	57,608.00
+ Margin on L,N Items 10.00% (\$\$)	5,752.80
Total Parts (\$\$)	63,360.80

Report was unsubmitted during this print-out.
Generated using Merlmen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO LIFT UP FRT CABIN <i>see photo</i>	New	400 800.00
2	TO REMOVE & FIX FRT WINDSCREEN	Repair	150 250.00
3	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	3000 3,500.00
4	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1750 2,600.00
5	TO CHECK WIRING	New	60 100.00
6	TO DIAGNOSE & CLEAR ERROR	New	150 200.00
Gross Labour Cost (\$\$)			7,450.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Revised
By 900100 GS
16 days
P/P
30/03/23 P 1645
EXCES: 2000
Revised
Reby before print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	396N
Vehicle No.:	XE7119K
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Mar 2023
Vehicle Make:	SCANIA
Vehicle Model:	P410A4X2NZ
Primary Colour:	Multicolor
Manufacturing Year:	2021
Engine No.:	DC13163L017337985
Chassis No.:	YS2P4X20009296067
Maximum Power Output:	-
Open Market Value:	\$107,725.00
Original Registration Date:	25 Feb 2022
First Registration Date:	25 Feb 2022
Transfer Count:	0
Actual ARF Paid:	\$5,387.00

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

COE Expiry Date:	24 Feb 2032
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
COE Paid:	\$25,578.00
COE Rebate Amount:	\$22,770.00
Total Rebate Amount:	\$22,770.00

Information contained herein is correct as at 31 Mar 2023

OK