LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Khong Lin Hui Lynn Date: 04 Apr 2023

Preliminary Advice

Vehicle No : SCM1818Y Accident Date : 27/03/2023

Make : BMW X3 Policy No.

DMPCSNW00246842200

: S\$0.00 Assignment Date : 30/03/2023 **Excess**

: 7 Date of Inspection : 31/3/2023 Est. Duration of Repair

Inspection At : DING AUTO PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,711.18
Revised Amount	:S\$	13,249.08
Check Items (Estimated)	:S\$	7,976.30
Total	:S\$	21,225.38

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 58,000.00 COE / PARF Rebate :S\$ 40,276.00

Salvage Value :S\$

Margin for Repair :S\$ 17,724.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let
		us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Lump Sum Repair

> Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.

Repairer able to undertake the repair within the nett value