

Ding Auto Pte Ltd
Sin Ming Industrial Est. Sec C, Blk
10, #01-20
575645

Insurer Reference:
Repairer Reference: 059255
Date calculated: 29/03/2023 5:17 PM



Full Report
Registration: SCM1818Y
Printed: 29/03/2023 5:17 PM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:		Date of Incident:	27/03/23
Estimated Repair Time:	12	Hire Car Start:	
Actual Repair Days:	12	Hire Car End:	

Vehicle Details

Vehicle
Manufacturer: BMW
Model: X3 (F25)
Sub Model: X3 XDRIVE 28I
Model Sheet Number: 01 XC 01
Registration: SCM1818Y
VIN number:
Odometer: 121615
Model Specs
2.0 LTR 180KW

Not Authorize
L1 Sing &
Repairing After Paint
7 days
Ex TRA

Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
32 00 590	ELECTRONIC TRACK AND WHEEL ALIGNMENT (WITHOUT: ADJUSTMENT)		16.0	56.00
41 11 071	RENEW L/ENGINE SUPPORT IN FRONT OF FRONT WALL AND WHEELHOUSE (WITHOUT SUSPENSION ALIGNMENT) (WITHOUT STRAIGHTENING DEVICE) INCLUDES: R + R ENGINE, GEARBOX, COMPLETE FRONT AXLE, FRONT PANEL, FRONT WING AND BONNET, ALIGN AND WELD WHEELHOUSE AND ENGINE SUPPORT, BLEED BRAKE		311.0	1,088.50
51 11 675	RENEW COMPLETE FRONT BUMPER COVER (FRONT BUMPER REMOVED)		13.0	45.50
51 71 538	R + R R/F WHEELHOUSE COVER FRONT		4.0	14.00
41 61 501	REPLACE BONNET (WITH BONNET REMOVED)		9.0	31.50
41 61 520	RENEW R/BONNET HINGE (BONNET REMOVED)		2.0	7.00
51 13 616	R + R COWL COVER		5.0	17.50

	Description	WU	Price SGD
NO NUMBER	INCLUDES: R + R WIPER ARMS R + R ENGINE COMPARTMENT PARTITION PANEL	3.0	10.50
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	28.90	347.0
	Alignment	1.30	16.0
	Measuring Work		56.00
	Total of Labour		1,270.50

Paint

Paint Work

Time Basis 12 WU/h

Code	Description - MF	WU	Price SGD
99 68 529	FRONT BUMPER COVER PAINTING STAGE 2	14.0	49.00
LE 0313	FRT TOWING EYE COVER PAINTING STAGE 2	1.0	3.50
99 61 529	BONNET PAINTING STAGE 2	26.0	91.00
99 35 519	L/F WING PAINTING STAGE 2	9.0	31.50
99 80 529	L/F WHEELHOUSE CPL PAINTING STAGE 1	5.0	17.50
LE 1226	R/LWR RADIATOR BRKT PAINTING STAGE 2	3.0	10.50
99 000	ADDITIONAL TIME FOR ONE MAIN WORK INCLUDES: MIX COLOUR AND SPRAY COLOUR SAMPLE	21.0	73.50

Total Paint

Hrs 6.60 WU 79.0 Price SGD 276.50

Material Cost - Paint

New Part Painting

Repair Painting

Material-constant Metal

Total

Price SGD

160.39

12.42

13.47

186.28

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2023-03-17	Price SGD
0260	FRONT NUMBER PLATE	KNPL3	Original	RM 30.00	X
0283	FRT NO PLATE BRKT	51 13 7 237 944	Original	RM 45.00	X
0284	FRONT BUMPER COVER	51 11 7 210 451	Original	RM 1,680.00	✓
0291	LOWER BUMPER COVER	51 11 7 210 441	Original	RM 390.00	✓
0292	L/F BUMPER BRACKET	51 11 7 308 081	Original	RM 45.00	✓
0303	R/F BUMPER BRACKET	51 11 7 308 082	Original	RM 45.00	X
0305	FRONT UPP AIR GRILLE	51 11 7 210 466	Original	RM 7 150.00	✓
0307	FRONT LWR AIR GRILLE	51 11 7 210 462	Original	RM 7 145.00	✓
0313	L/BUMPER AIR GRILLE	51 11 7 210 469	Original	RM 120.00	X
0326	FRT TOWING EYE COVER	51 11 7 210 474	Original	RM 55.00	X
0336	R/F AIR DUCT	51 74 7 210 488	Original	RM 110.00	✓
0340	FRONT BUMPER SUPPORT	51 11 2 575 934	Original	RM 650.00	✓
0367	FRT UPP IMPACT DAMP	51 64 7 210 496	Original	RM 7 105.00	✓
0415	L/F VENT DUCT	51 74 7 210 485	Original	RM 7 90.00	✓
	L/F GRILLE	51 11 7 210 725	Original	RM 160.00	✓

NGA

NOTICE
port code
n must be
on provid
ity.
e and ac
report
port will t
copies of
lodgement

of Su
orted
e of A
act Lo
dition
country

Vehi

Is
N
t

Code	Description	Part Number	Part Source	Price SGD
0416	R/F GRILLE	51 11 7 210 726	Original	DD 160.00 ✓
0431	GRILLE BADGE	51 14 8 132 375	Original	100.00 ✓
0471	BONNET	41 61 7 267 337	Original	B 2,600.00 ✓
0475	L/BONNET HINGE	41 61 7 262 875	Original	DR 135.00 ✓
0476	R/BONNET HINGE	41 61 7 262 876	Original	R 135.00 X
0491	L/UPPER LOCK	51 23 7 210 733	Original	DR 105.00 ✓
0492	R/UPPER LOCK	51 23 7 210 734	Original	DR 105.00 X
0495	LEFT ADJUSTER	51 76 7 183 752	Original	DR 15.00 X
0496	RIGHT ADJUSTER	51 76 7 183 752	Original	DR 15.00 X
0497	L/F BONNET STRUT	51 23 7 210 727	Original	DR 180.00 X
0503	L/BONNET LOCK	51 23 7 224 883	Original	DR 85.80 ✓
0504	R/BONNET LOCK	51 23 7 224 883	Original	DR 85.80 ✓
0527	BONNET FRT GASKET	51 76 7 210 737	Original	DR 65.00 ✓
0529	L/OUTER BONNET SEAL	51 76 7 234 367	Original	DR 45.00 ✓
0561	LEFT HEADLAMP ASSY	63 12 7 217 289	Original	CM 3,250.00 ✓
0562	RIGHT HEADLAMP ASSY	63 12 7 217 290	Original	CM 3,250.00 ✓
0595	L/F S/PANEL BRKT FRT	41 35 7 267 327	Original	DR 95.00 ✓
0597	L/F CTR S/PANEL BRKT	41 35 7 267 335	Original	DR 95.00 X
0599	L/F S/PANEL BRKT RR	41 00 7 267 113	Original	DR 145.00 X
0601	L/F LWR S/PANEL BRKT	41 35 7 267 325	Original	DR 95.00 X
0603	L/R IN LWR S-PNL EXT	41 00 7 267 115	Original	DR 145.00 X
0605	L/R UPP S/PANEL BRKT	41 00 9 624 949	Original	DR 140.00 X
0607	L/F FOG LAMP	63 17 7 238 787	Original	CM 395.00 ✓
0645	L/FOG LAMP BRACKET	51 11 7 212 955	Original	CM 125.00 ✓
0709	L/F REPEATER LAMP	63 13 7 171 007	Original	DR 165.00 ✓
0741	L/F WING	41 35 7 267 323	Original	DR 1,150.00 ✓
0787	L/F WHEELARCH TRIM	51 77 7 210 081	Original	DR 225.00 ✓
0835	L/F AIR VENT GRILLE	51 71 7 213 647	Original	DR 25.00 X
0841	L/F W-HOUSE CVR FRT	51 71 7 213 641	Original	DR 175.00 X
0843	L/F W-HOUSE RR COVER	51 71 7 213 643	Original	DR 175.00 X
0845	L/F LIP	51 62 7 213 653	Original	DR 20.00 X
1009	FRONT PANEL	51 74 7 210 476	Original	CM 695.00 ✓
1017	FRT CONNECTING STRUT	51 64 7 210 501	Original	DR 240.00 ✓
1018	RR CONNECTING STRUT	51 64 7 210 502	Original	DR 220.00 X
1019	L/F PANEL SUPPORT	51 64 7 210 503	Original	DR 55.00 X
1020	R/F PANEL SUPPORT	51 64 7 210 504	Original	DR 55.00 X
1111	L/F WHEELHOUSE CPL	41 10 7 266 997	Original	DR 2,280.00 X
1131	L/F SUPPORT MEMBER	41 11 7 376 619	Original	DR 285.00 X
1153	L/SUPP BEAM REP KIT	USE SINGLE PARTS		
1155	L/SUPPORT ADHESIVE	83 19 0 413 015		DR 381.70 X
1157	L/SUPP BLIND RIVET	83 19 0 301 414		DR 23.85 X
1159	L/SUPP BLIND RIVET	83 19 0 301 421		DR 1.65 X
1161	L/SUPP BEAM P/RIVET	83 19 2 158 079		DR 9.90 X
1163	L/CARRIER EMC SCREW	83 19 0 301 639		DR 1.10 X
1165	L/SUPPORT CLEANER	83 19 2 211 217		DR 26.15 X
1187	L/HEADLAMP MOUNTING	51 64 7 210 499	Original	CM 245.00 ✓
1188	R/HEADLAMP MOUNTING	51 64 7 210 500	Original	DR 245.00 X
1189	L/F ADAPTER PLATE	51 64 7 210 507	Original	DR 45.00 X
1190	R/F ADAPTER PLATE	51 64 7 210 508	Original	DR 45.00 X
1226	R/LWR RADIATOR BRKT	41 11 7 267 087	Original	DR 105.00 X
1363	CTR LOWER PARTITION	51 75 7 213 660	Original	DR 101.95 X
1365	CTR UPPER PARTITION	51 75 7 213 661	Original	DR 120.00 X
1369	L/ENG COMP PARTITION	51 71 7 213 663	Original	DR 180.00 X
7761	RADIATOR	17 11 8 623 369	Original	DR 740.00 X
7769	L/RADIATOR BRACKET	17 11 7 593 838	Original	DR 95.00 X
7770	R/RADIATOR BRACKET	17 11 7 593 839	Original	DR 95.00 X

Description	Part Number	Part Source	Price SGD
ELECTRIC FAN CPL	17 42 7 601 176	Original	1,850.00 X
INTERCOOLER	17 51 7 823 570	Original	650.00
L/AIR COOLER HOSE	13 71 7 605 044	Original	580.00
L/BRACKET	51 75 7 213 677	Original	60.00 X
HIGH TONE HORN	61 33 7 217 703	Original	95.00 X
HEADLAMP MODULE LH	MODULE	Original	680.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal

0.00
27,527.90

Total

27,527.90

Extras

Code	Description	Price SGD
1001	DIAGNOSIS/RE-PROGRAM HEADLAMP MODULE	320 ? 450.00*
	Total Extras	450.00

Final Calculation

	SGD	SGD
Parts	27,527.90	
Total Parts		27,527.90
Labour Time Base 12 WU/h		
Total 347.0 WU X 42.00 SGD/h	1,214.50	
Alignment		
Measuring Work	56.00	
Total of Labour		1,270.50
Total Of Extras		450.00
Paint Work Time Base 12 WU/h		
Labour Cost 79.0 WU X 42.00 SGD/h	276.50	
Material Cost	186.28	
Total Paint Including Material		462.78
Repair Cost Excludes GST		29,711.18
GST (+8.0%)		2,376.89
Repair Cost Included GST		32,088.07

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ding Auto Pte Ltd

PARTS SUPPLEMENTARY & QUOTATION FORM

ATTENTION: Kenneth Kong @ LFK	WORK ORDER NUMBER:
VEHICLE NUMBER: SCN 1818Y	OUR REFERENCE NUMBER:
MAKE & MODEL: BMW X3	

S/NO	PART NUMBER	PART DESCRIPTION	QTY	UNIT PRICE	SURVEYOR REMARK	W/S REMARK
1		F/Bumper Nozzle Jet LH	1	\$ 140.00	CMA ✓	
2		F/Bumper Nozzle Cap LH	1	\$ 70.00	211 ✓	
3		F/Bumper Support Adapter RH	1	\$ 220.00	A ✓	
4		F/Bumper Support Adapter LH	1	\$ 220.00	AT ✓	
5		F/Bumper parking sensor	1	\$ 360.00	CA ✓	
6		harness wire cpl				
7		Headlamp - Repair Kit LED	1	\$ 400.00	CMA ✓	
8		module - High beam				
9		Headlamp - Repair Kit LED	1	\$ 400.00	CA ✓	
10		module - Low beam				
11		Headlamp driver module	1	\$ 680.00	Refer estimate	
12						
13						
14						
15						
16						
17						
18						

AUTO

Ding Auto Pte Ltd
Sin Ming Industrial Est. Sec C, Blk
10,#01-20
575645



Insurer Reference:
Repairer Reference: 059255
Date calculated: 03/05/2023 3:30 PM

Full Report
Registration: SCM1818Y
Printed: 03/05/2023 3:30 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:		Date of Incident:	27/03/23
Estimated Repair Time:	12	Hire Car Start:	
Actual Repair Days:	12	Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	X3 (F25)
Sub Model:	X3 XDRIVE 28I
Model Sheet Number:	01 XC 01
Registration:	SCM1818Y
VIN number:	
Odometer:	121615

Model Specs

2.0 LTR 180KW

Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
41 35 550	RENEW L/F WING INCLUDES: R + R WHEELARCH TRIM, SIDE INDICATOR AND A-PILLAR MOULDING		8.0	28.00
41 33 040	RENEW FRONT PANEL INCLUDES: R + R BUMPER CARRIER AND BOTH HEADLAMP MOUNTS		30.0	105.00
51 11 675	RENEW COMPLETE FRONT BUMPER COVER (FRONT BUMPER REMOVED)		13.0	45.50
41 61 600	R + R BONNET		4.0	14.00
41 61 501	REPLACE BONNET (WITH BONNET REMOVED)		9.0	31.50
41 61 520	RENEW L/BONNET HINGE (BONNET REMOVED)		2.0	7.00
41 61 520	RENEW R/BONNET HINGE (BONNET REMOVED)		2.0	7.00
NO NUMBER	R + R BONNET SEAL		1.0	3.50

Labour Cost
Panel / Mechanical Labour

Hrs	WU	
5.80	69.0	241.50
Total of Labour		241.50

Paint

Paint Work

Code	Description - MF	Time Basis 12 WU/h	
		WU	Price SGD
99 68 529	FRONT BUMPER COVER PAINTING STAGE 2	14.0	49.00
99 61 529	BONNET PAINTING STAGE 2	26.0	91.00
99 35 519	L/F WING PAINTING STAGE 2	9.0	31.50
99 99 000	ADDITIONAL TIME FOR ONE MAIN WORK INCLUDES: MIX COLOUR AND SPRAY COLOUR SAMPLE	21.0	73.50

Total Paint	Hrs	WU	Price SGD
	5.80	70.0	245.00

Material Cost - Paint

New Part Painting	Price SGD
Material-constant Metal	159.96
Total	13.47
	173.43

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2023-04-17
				Price SGD
0283	FRONT BUMPER COVER	51 11 7 210 451	Original	1,680.00
0284	LOWER BUMPER COVER	51 11 7 210 441	Original	390.00
0291	L/F BUMPER BRACKET	51 11 7 308 081	Original	45.00
0303	FRONT UPP AIR GRILLE	51 11 7 210 466	Original	150.00
0305	FRONT LWR AIR GRILLE	51 11 7 210 462	Original	145.00
0326	R/F AIR DUCT	51 74 7 210 488	Original	110.00
0336	FRONT BUMPER SUPPORT	51 11 2 575 934	Original	650.00
0340	FRT UPP IMPACT DAMP	51 64 7 210 496	Original	105.00
0367	L/F VENT DUCT	51 74 7 210 485	Original	90.00
0415	L/F GRILLE	51 11 7 210 725	Original	160.00
0416	R/F GRILLE	51 11 7 210 726	Original	160.00
0431	GRILLE BADGE	51 14 8 132 375	Original	100.00
0471	BONNET	41 61 7 267 337	Original	2,600.00
0475	L/BONNET HINGE	41 61 7 262 875	Original	135.00
0491	L/UPPER LOCK	51 23 7 210 733	Original	105.00
0492	R/UPPER LOCK	51 23 7 210 734	Original	105.00
0503	L/BONNET LOCK	51 23 7 224 883	Original	85.80
0504	R/BONNET LOCK	51 23 7 224 883	Original	85.80
0529	L/OUTER BONNET SEAL	51 76 7 234 367	Original	45.00
0561	LEFT HEADLAMP ASSY	63 12 7 217 289	Original	3,250.00
0595	L/F S/PANEL BRKT FRT	41 35 7 267 327	Original	95.00
0637	L/F FOG LAMP	63 17 7 238 787	Original	395.00
0645	L/FOG LAMP BRACKET	51 11 7 212 955	Original	125.00
0741	L/F WING	41 35 7 267 323	Original	1,150.00
0787	L/F WHEELARCH TRIM	51 77 7 210 081	Original	225.00
1009	FRONT PANEL	51 74 7 210 476	Original	695.00

Code	Description	Part Number	Part Source	Price SGD
1017	FRT CONNECTING STRUT	51 64 7 210 501	Original	240.00
1187	L/HEADLAMP MOUNTING	51 64 7 210 499	Original	245.00
1000	HEADLAMP MODULE LH	MODULE	Original	680.00
1002	F/BUMPER NOZ. JET LH	NOZZLE JET	Supplementary	140.00
1003	F/BUMPER NOZ CAP LH	NOZZLE CAP	Supplementary	70.00
1004	F/BUMP ADAPTER RH	SUPPORT ADAPTER	Supplementary	220.00
1005	F/BUMP ADAPTER LH	SUPPORT ADAPTER	Supplementary	220.00
1006	FRT P/SENSOR HARNESS	HARNESS	Supplementary	360.00
1007	LAMP HIGH LED MODULE	MODULE	Supplementary	400.00
1008	LAMP LOW LED MODULE	MODULE	Supplementary	400.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	15,856.60
Total	15,856.60

Extras

Code	Description	Price SGD
1001	DIAGNOSIS/RE-PROGRAM HEADLAMP MODULE	320 450.00*
Total Extras		450.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	15,856.60	15,856.60
Labour Time Base 12 WU/h		
Total 69.0 WU X 42.00 SGD/h	241.50	
Total of Labour		241.50
Total Of Extras		450.00
Paint Work Time Base 12 WU/h		
Labour Cost 70.0 WU X 42.00 SGD/h	245.00	
Material Cost	173.43	
Total Paint Including Material		418.43
Repair Cost Excludes GST		16,966.53
GST (+8.0%)		1,357.32
Repair Cost Included GST		18,323.85

11 Rm @ 13,450/h BY excess

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.