



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23003339/Kny3q2	
			Date: 14/04/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBV 1301K	Veh. Inspected	SNG 2351X
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2301267/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	30/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA AXIO (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	NKE1657258674	Colour	METALLIC SILVER
	Odometer	57100 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	TERAFLEX	8 mm
	L/H Front Tyre	185/60 R15	TERAFLEX	8 mm
	R/H Rear Tyre	185/60 R15	TOURADOR	7 mm
	L/H Rear Tyre	185/60 R15	TOURADOR	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/03/2023	Inspection Date	30/03/2023
	Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	