

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowork@gmail.com



MP053REH104514005

DATE : 29.03.2023

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLP8472S**
MODEL : **TOYOTA COROLLA ALTIS**
DATE OF ACCIDENT : 21.03.2023
TIME OF ACCIDENT : 08:10 HOURS

Hui Rong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehnd</i>	1	\$ 515.10	\$ 515.10
2	REAR BUMPER REFLECTOR <i>LH cndd</i>	2	\$ 75.10	\$ 150.20
3	REAR BUMPER SIDE RETAINER <i>Deu</i>	2	\$ 105.10	\$ 210.20
4	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 395.10	\$ 395.10
5	REVERSE SENSOR <i>Dnd 1 piece</i>	2	\$ 311.10	\$ 622.20
6	REVERSE SENSOR HOLDER <i>nu</i>	2	\$ 69.30	\$ 138.60
7	REVERSE SENSOR WIREHARNES <i>Deu</i>	1	\$ 437.50	\$ 437.50
8	BOOTLID <i>Buckle d</i>	1	\$ 756.10	\$ 756.10
9	BOOTLID DETECTOR <i>Cndd</i>	1	\$ 385.00	\$ 385.00
10	BOOTLID LOGO <i>2</i>	1	\$ 85.00	\$ 85.00
11	BOOTLID EMBLEM 'COROLLA' <i>Deu</i>	1	\$ 70.00	\$ 70.00
12	BOOTLID EMBLEM 'ALTIS'	1	\$ 70.00	\$ 70.00
13	BOOT LID HINGE <i>Deu nu</i>	2	\$ 70.00	\$ 140.00
14	BOOTLID TOP LOCK <i>Dnd</i>	1	\$ 318.10	\$ 318.10
15	BOOTLID LOWER LOCK <i>Deu nu</i>	1	\$ 20.00	\$ 20.00
16	BOOTLID WEATHERSTRIP <i>ht</i>	1	\$ 195.00	\$ 195.00
17	TAILLAMP <i>LH ut</i>	2	\$ 465.00	\$ 930.00
18	TAILLAMP LOWER BARCKET <i>Deu nu</i>	2	\$ 115.10	\$ 230.20
19	REAR FENDER INNER COWLING <i>3M</i>	2	\$ 350.20	\$ 700.40
20	REAR FENDER INNER TRIM <i>Deu</i>	2	\$ 770.10	\$ 1,540.20
21	REAR END PANEL <i>Dented</i>	1	\$ 695.30	\$ 695.30
22	REAR END PANEL TOP GARNISH <i>Dehnd</i>	1	\$ 250.10	\$ 250.10

Handwritten notes and checkmarks on the right side of the table:
- Next to row 1: ✓
- Next to row 2: 25.10
- Next to row 3: ✓
- Next to row 4: ✓
- Next to row 5: 255
- Next to row 6: 50
- Next to row 7: ✓
- Next to row 8: ✓
- Next to row 9: 155
- Next to row 10: ✓
- Next to row 11: ✓
- Next to row 12: ✓
- Next to row 13: ✓
- Next to row 14: 318.10 (circled)
- Next to row 15: ✓
- Next to row 16: ✓
- Next to row 17: 465
- Next to row 18: ✓
- Next to row 19: ✓
- Next to row 20: ✓
- Next to row 21: ✓
- Next to row 22: ✓

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLP8472S**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 21.03.2023
 TIME OF ACCIDENT : 08:10 HOURS

23	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 271.10	\$ 271.10
----	---------------------------------------	---	-----------	-----------

4389.90
3292.42

TOTAL PRICE \$ 9,125.40
 LESS 25% \$ 2,281.35
SUB TOTAL PRICE \$ 6,844.05

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
4	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
5	REAR FENDER COWLING CLIPS (SET) <i>gap</i>	1	\$ 80.00	\$ 80.00
6	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
7	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
8	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00

120

TOTAL \$ 660.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 200.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 200.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 100.00	<i>50</i>
8	TRANSFER BOOTLID MECHANISM	\$ 100.00	<i>60</i>

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLP8472S**
MODEL : **TOYOTA COROLLA ALTIS**
DATE OF ACCIDENT : 21.03.2023
TIME OF ACCIDENT : 08:10 HOURS

9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

1910

TOTAL

\$ 3,900.00

TOTAL PARTS COST : \$ 7,504.05
TOTAL LABOUR COST : \$ 3,900.00
TOTAL REPAIR COST : \$ 11,404.05

Adrian Lj
L/S 30/03/23.
06 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP:8297 9787

total: 5322.42
L/S: 4250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4250