



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNG6478M

ALLIANZ INSURANCE SINGAPORE PTE.  
LTD.  
MOTOR CLAIM DEPARTMENT  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897  
67143369

### Vehicle & Document Information

WIP No **63970**  
Reg No/Reg Date **SNG6478M / 24/08/2022**  
Date In/Mileage **/ 0**  
Chassis No **W1K1770842J3623022**  
Engine No **28291480822806**  
Make/Model **MB/A 180 COMPACT SALOON**  
Colour/Trim **026 667 Denim Blue / 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000001	Credit	30/03/2023/ 09:50	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : SP2003915046 // 23-03-2023 DRIVE IN/EXCESS : 30-03-2023 // TBA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :							0.10	380.00
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT								1440.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.							0.07	1000.00
A BPIRES RESPRAY REAR BUMPER					1.00	1353.60	00.00	1353.60
M REAR BUMPER					1.00	281.47	00.00	281.47
M REAR BOTTOM PANEL					1.00	70.05	00.00	70.05
M RH/F BASIC CARRIER FOR BUMPER					1.00	131.94	00.00	131.94
M RH/F BUMPER SIDE BRACKET					1.00			

**Alan Quek**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
Tel: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **4,657.06**  
8% GST on **4657.06** **372.56**  
**Total Payable 5,029.62**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG