



KOMODO MOTORS PTE. LTD.

221, Kinnery Road, #01-01, Singapore 730226
Tel: 65 6473 3288 Fax: 65 6473 1613 Email: kmm@komodo.sg
GST No: 196459538

(GST REGISTRATION NO: MR-8500364-4)

Date : 30 MAR 2023

Lonpac Insurance Bhd

Attn: Motor Claims Department

Vehicle number : **SJS 19 D**
Make and model : IONIQ 5 ELECTRIC AWD
Registration Date : 08/12/2021
Chassis number : KMHKM81CRNU045737
Engine number : EM17MAC3931D

Claim Officer : Boon Chin
Job No. :
Owner name : Doreen Tan Lay Pe
Date of Acc : 29/03/2023
Policy number : A 300745341 AH1
Claim Type **Third Party Claim**

Items :

		2nd	Estimate	Revised
1	FRONT BUMPER CLIP X10	865952T500	\$ 12.00	all ✓
2	UPPER GRILLE CLIP X6	1420608250B	\$ 3.60	new ✓
3	COVER-FR BUMPER	86510GI000	\$ 376.30	ty ✓
4	BRACKET-REINF	86535GI010	\$ 23.50	? x SVC
5	PIECE-RADIATOR GRILLE,RH	863A8GI010	\$ 34.10	new ✓
6	LAMP ASSY-FRONT AUXILIARY,RH	92109GI000	\$ 1,856.60	new ✓
7	BRACKET-FR BUMPER SIDE,RH	86552GI000	\$ 22.20	new ✓
8	GRILLE-RADIATOR	86351GI010CA	\$ 784.60	? }
9	ULTRASONIC SENSOR-S.P.A.S SIDE	99350L1000YEV	\$ 176.40	? } x SVC
10	UNIT ASSY-FRONT CORNER RADAR,R	99130GI100	\$ 819.80	? }
11	WIRING HARNESS-FR BUMPER	91890GI880	\$ 922.90	? }
12	LAMP ASSY-HEAD,RH	92102GI120	\$ 3,001.90	new ✓
13	CLIP-HEAD LAMP MTG	92173F2000	\$ 2.00	new ✓
14	CARRIER ASSY-FRONT END MODULE	64101GI000	\$ 933.90	? x SVC
15	PANEL ASSY-HOOD	66400GI000	\$ 3,442.60	bt ✓
16	HINGE ASSY-HOOD,LH	66910GI000	\$ 172.80	? }
17	HINGE ASSY-HOOD,RH	66920GI000	\$ 172.80	? } x SVC
18	BUMPER-HOOD OVERSLAM x4	86410T1500	\$ 37.20	? }
19	BUMPER-HOOD OVERSLAM x2	86410T1000	\$ 12.40	ty ✓
20	BUMPER ASSY-HOOD STOP x2	86450GI000	\$ 20.20	? x SVC
21	CLIP-HOOD INSULATING PAD MTG x10	8112637010	\$ 11.00	new ✓
22	PANEL-FENDER,RH	66321GI000	\$ 587.60	bt ✓
23	GUARD ASSY-FRONT WHEEL,RH	86812GI000	\$ 130.60	de ✓
24	CLIP (for wheel guard)	1420608250B	\$ 0.60	new ✓
25	GARNISH ASSY-FNDR SIDE,RH	87712GI220	\$ 367.00	mis ✓
			\$ 13,924.60	
Less 20% Discount			\$ 2,784.92	\$ -
Material total			\$ 11,139.68	\$ -

Vehicle number : SJS 19 D

Body, Paint & Labour Items :

	Estimate	Revised
1 To carry out accident body repair - FRONT BUMPER, SUPPORT PANEL, BONNET, RHF FENDER & RHF FENDER APRON (\$570 per day - EV Ioniq 5)	\$ 3,420.00	2280 ✓
2 Complete putty and spray paint all affected areas - FRONT BUMPER, BONNET, RHF FENDER & RHF FENDER APRON (\$420 per panel - EV Ioniq 5)	\$ 2,520.00	1680 ✓

Labour Charges:

	2nd	Estimate	Revised
3 TO REFOCUS BOTH FRT HEAD LAMP (S.NETT)		\$ 40.00	✓✓
4 TO SUPPLY BONNET SEALANT (S.NETT)		\$ 100.00	✓✓
5 TO VACUUM & TOP UP AIRCON GAS (S.NETT)		\$ 650.00	✗
6 TO SUPPLY SEALANT ON THE CUTTING AREA (S.NETT)		\$ 280.00	✗
7 TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUC) (S.NETT)		\$ 280.00	✗
8 TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING (S.NETT)		\$ 220.00	✓✓
9 TO REPROGRAMME AFTER THE ACCIDENT REPAIR (S.NETT)		\$ 220.00	✓✓
10 SUNDRIES (S.NETT)		\$ 40.00	20 ✓
11			
Total Labour		\$ 7,770.00	\$ -
Total Parts		\$ 11,139.68	\$ -
Excess		\$ -	\$ -
		\$ 18,909.68	\$ -
Add GST 8%		\$ 1,512.77	\$ -
Grand Total		\$ 20,422.45	\$ -

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***

Tanjin 92495749/62563581

wp- 10/4/23 @ 1700

P/P Resurvey before paint

7-8 days

Tanjin @ lkk auto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: