



Case Details

Case Reference Number : TAX/01/23/2060
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5490E

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-20366-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : income insurance limited
 Accident Date and Time : 26/01/2023 01:40 PM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, FR BUMPER	1	560.30	560.30	25.00	420.22	Replace	1	420.22	Replace	de ✓
Standard	Main			SUPPORT, FR BUMPER LH	1	86.20	86.20	25.00	64.65	Replace	0	0	Check	gun
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	ner ✓
Standard	Main			LAMP ASSY, FOG, LH	1	1,029.90	1,029.90	10.00	926.91	Replace	0	0	Not Give	Xun
Standard	Main			UNIT, HEADLAMP, LH	1	2,852.40	2,852.40	10.00	2,567.16	Replace	0	0	Not Give	Xun
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	1,039.90	1,039.90	10.00	935.91	Replace	0	0	Not Give	Xun
Standard	Main			FENDER SUB-ASSY, FR, LH	1	1,060.70	1,060.70	25.00	795.53	Replace	1	795.53	Replace	ht ✓
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	59.10	59.10	25.00	44.33	Replace	1	44.33	Replace	ner ✓
Standard	Main			LINER, FR FENDER, LH	1	219.10	219.10	25.00	164.33	Replace	0	0	Check	2 ✓
Standard	Main			PAD, FR WHEEL LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Check	2 } unx
Standard	Main			SEAL SUB-ASSY, LH	1	56.20	56.20	25.00	42.15	Replace	0	0	Check	2 }
Standard	Main			PROTECTOR, FR FENDER LH	1	101.80	101.80	25.00	76.35	Replace	0	0	Not Give	Xun
Standard	Main			CAP SUB-ASSY, WHEEL	1	229.00	229.00	25.00	171.75	Replace	1	171.75	Replace	ant ✓
Standard	Main			WHEEL, DISC FRONT	1	2,036.30	2,036.30	25.00	1,527.23	Replace	0	0	Not Give	Xun
Total Spare Part Cost									10,001.97	Surveyor Total			1,467.83	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									7,507.66	Final Sur Total			1,174.26	

https://va3swb3.sm...

SMRT Recommendation													Surveyor Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	Xun
Standard	Main			HUB & BEARING ASSY, RH & LH	1	722.10	722.10	25.00	541.58	Replace	0	0	Not Give	Xun
Standard	Main			KNUCKLE, STEERING, LH	1	717.50	717.50	25.00	538.13	Replace	0	0	Not Give	Xun
Standard	Main			ABSORBER SET, SHOCK, FRONT LH	1	475.80	475.80	25.00	356.85	Replace	0	0	Not Give	Xun
Standard	Main			LOWER ARM SUB-ASSY, FRONT LH	1	823.20	823.20	25.00	617.40	Replace	0	0	Not Give	Xun.
Total Spare Part Cost									10,001.97	Surveyor Total			1,467.83	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				
Final Spare Part Cost									7,507.66	Final Sur Total			1,174.26	
1467.84														

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	1,014.00	300.00	
Total:			1,014.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
3	Main	RESPRAY WHEEL CAP	180.00	0	Xun
4	Main	TO RESPRAY RIM	180.00	0	Xun
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	Xun REQ INVOICE
2	Main	TO WASH AND VACUUM	60.00	0	Xun
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	Xun
Total:			756.00	110.00	

Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1: REC Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
5 Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	80	
6 Main	TO REMOVE AND REFIX UNDERCARRIAGE	200.00	200	
7 Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:		756.00	110.00	110

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	7,507.66	1,174.26
Total Labour Cost	1,014.00	300.00
Total Spray Painting	1,116.00	400.00
Other	756.00	110.00
Overall Total	10,393.66	1,984.26
Lump Sum Repair Option		☒
Lump Sum Total	10,400.00	2,000.00
Surveyor Approved Amount		2,000.00
No of Repair Days*	6	3
Remarks	-	LUMPSUM REPAIR / AFTER PAINT PHOTOS ,FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR TAUFIKH HP 9740 57401 EMAIL : tau@lkk.com.sg
Surveyor Name		Taufikh
Signature		

Survey Date

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Save

Clear

1467.84

300

400

110

2277.84

20% 45\$ 1800

03 days *

Taufikh 974057401

wp' 30/1/23 @ 300pm

3 days

4/5 Resurvey the repair