



Section A - Accident Details

Registration Number	SHB5627D
Case Reference Number	TAX/01/23/2061
Registration Date	30/Nov/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	YEN SOON WENG
Type of Accident	Head To Side
Accident Date and Time	26/Jan/2023 5:15 PM
Accident Reported Date and Time	27/Jan/2023 12:05 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117506
Special Instruction to ARC, if any	LEFT SIDE FRONT
Prepared Date and Time	27/Jan/2023 6:18 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$300.00
Total Spray Cost	\$1,494.00	\$700.00
Total Spare Part Cost	\$10,095.67	\$140.33
Total Other Cost	\$1,088.44	(\$190.33)
TOTAL COST	\$13,692.11	\$950.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / INCOME
ARC / Surveyor Sign Off Date	30/01/2023 4:42 PM	30/01/2023 3:40 PM
Signature		
Remarks	LUMSUMP REPAIR / AFTER PAINT PHOTOS ,FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR TAUFIKH , HP 9749 5749/ EMAIL: taufikh@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2302-0258	Invoice Number	
Quotation Date	22.02.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,014.00	\$300.00
Total Labour	\$1,014.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$1,494.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$270.33)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$80.00
TO REMOVE AND REFIT TYRE	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$148.44	\$0.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,088.44	(\$190.33)

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5211947962	COVER, FR BUMPER	1.00	\$560.30	100.00	\$0.00	Replace	Repair
		5211647050	SUPPORT, FR BUMPER LH	0.00	\$86.20	0.00	\$0.00	Replace	Check
		7531047060	EMBLEM ASSY FRONT	0.00	\$98.70	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		8122047020	LAMP ASSY, FOG, LH	0.00	\$1,029.90	0.00	\$0.00	Replace	Not Given
		8118547691	UNIT, HEADLAMP, LH	0.00	\$2,852.40	0.00	\$0.00	Replace	Not Given

R
X
X
√
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/03/2023

User ID : PohSuan

		5380247100	FENDER SUB-ASSY, FR , LH	1.00	\$1,060.70	100.00	\$0.00	Replace	Repair	R
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
		5387647110	LINER, FR FENDER, LH	0.00	\$219.10	0.00	\$0.00	Replace	Check	X
		5385247041	PAD, FR WHEEL LH	0.00	\$65.00	0.00	\$0.00	Replace	Check	X
		4261147450	WHEEL, DISC FRONT	1.00	\$2,036.30	100.00	\$0.00	Replace	Repair	R
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
		4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Not Given	X
		7586047900	MOULDING ASSY, BODY ROCKER PANEL , LH	0.00	\$649.10	0.00	\$0.00	Replace	Not Given	X
		4321247040	KNUCKLE, STEERING, LH	0.00	\$717.50	0.00	\$0.00	Replace	Not Given	X
		4806947060	LOWER ARM SUB-ASSY, FRONT LH	0.00	\$823.20	0.00	\$0.00	Replace	Not Given	X
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	100.00	\$0.00	Replace	Repair	R
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
Total					\$12,578.94		\$140.33			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	140.33	
+	300.00	
+	780.00	L/S \$950/-
	1,220.33	
	-20%	
	976.26	