

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0319/2023/EQ
DATE : 28-Mar-23
WIP : 13736

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR MOHAMED NOOR BIN AKBAR
ADDRESS : BLK 98 BEDOK NORTH AVENUE 4
#06-1902
SINGAPORE 460098
TELEPHONE : HP +65 97720046
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900141871
VEHICLE NO : **SMN 3130 K**
MODEL CODE : AUDI Q2 1.0 TFSI S-TRONIC
MODEL YEAR : 31/7/2019
ENGINE NO : CHZ C30340
CHASSIS NO : WAUZZZGA3KA061319
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Mar-23
PLACE OF ACCIDENT : BUKIT BATOK WEST AVE 5, OPPS HOMETEAM NS BT.BATOK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	X
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	800.00	560 ✓
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	X.
4	TO REMOBEVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	X
5	TO DISMANTLE AND RENEW REAR BUMPER, LHS FRONT DOOR AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. TO REPAIR LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,500.00	1000 ✓
6	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, TWO DOOR HANDLES, LHS WING MIRROR COVER, LHS SILL PANEL, LHS C-PILLAR OUTER TRIM, DRAIN CHANNEL, DOOR ENTRANCE, ROOF CHANNEL AND REAR END PANELLING.	\$	8,500.00	1800 ✓
TOTAL LABOUR CHARGES		:	\$ 20,280.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3130 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	X
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 20,752.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH <i>Dented</i>	1	\$ 3,137.00	✓ 2509.60
2	FRONT DOOR CATCH - LH <i>New</i>	1	\$ 141.00	? 112.80
3	FRONT DOOR INNER SEAL - LH <i>New</i>	1	\$ 189.00	✓ 150.80
4	FRONT DOOR ATTACHMENT PARTS <i>New</i>	1	\$ 104.00	+
5	FRONT WING MIRROR CAP - LH <i>Repis</i>	1	\$ 254.00	+
6	FRONT EXTERIOR WING MIRROR MOUNTING <i>3 new</i>	1	\$ 1,196.00	+
7	FRONT WING MIRROR GLASS - LH	1	\$ 251.00	+
8	FRONT DOOR COVER - LH <i>at</i>	1	\$ 286.00	238.80
9	FRONT DOOR EXTERIOR HANDLE - LH <i>new</i>	1	\$ 421.00	+
10	FRONT DOOR EXTERIOR HANDLE HOUSING - LH <i>new</i>	1	\$ 62.00	+
11	FRONT WINDOW REGULATOR - LH <i>new</i>	1	\$ 321.00	+
12	REAR DOOR - LH <i>Dented</i>	1	\$ 3,137.00	✓ 2509.60
13	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 159.00	✓ 127.20
14	BONDING AGENT <i>Not new</i>	1	\$ 51.00	? X
15	CLEANING SOLUTION <i>Not new</i>	1	\$ 80.00	? X
16	APPLICATOR <i>Not new</i>	1	\$ 9.00	? X
17	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 104.00	+
18	REAR DOOR CATCH - LH <i>New</i>	1	\$ 141.00	? 112.80
19	REAR DOOR OUTER SEAL - LH <i>Not new</i>	1	\$ 70.00	? X
20	REAR DOOR HINGE HALF UPPER PART - LH LOWER <i>new</i>	1	\$ 54.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,167.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3130 K

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR DOOR HINGE HALF LOWER PART - LH LOWER <i>AP</i>	1	\$ 57.00	✓	
22	REAR DOOR INNER SEAL - LH <i>new</i>	1	\$ 331.00	✓	
23	REAR DOOR COVER - LH <i>lit</i>	1	\$ 252.00	✓	201.50
24	REAR WINDOW REGULATOR - LH <i>new</i>	1	\$ 321.00	✓	
25	REAR SIDE PANEL - LH <i>Regis</i>	1	\$ 2,813.00	✓	
26	REAR PILLAR C TRIM - LH <i>new</i>	1	\$ 735.00	✓	
27	REAR SIDE MEMBER TRIM - LH <i>missing</i> <i>NE new</i>	1	\$ 266.00	✓	? <i>X</i>
28	REAR WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 237.00	✓	
29	REAR BUMPER	1	\$ 1,442.00	✓	
30	REAR BUMPER SPOILER	1	\$ 335.00	✓	
31	REAR BUMPER REFLECTOR - LH	1	\$ 36.00	✓	
32	REAR BUMPER GUIDE SECTION - LH	1	\$ 64.00	✓	
33	REAR WHEEL COVER - LH / RH <i>LH missing</i>	2	\$ 380.00	✓	190. 152
34	REAR ALUMINIUM RIM - LH <i>new</i>	1	\$ 1,080.00	✓	
35	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	✓	
36	ACRYLIC SEALANT	S/N	\$ 180.00	✓	
37	CAVITY WAX	S/N	\$ 140.00	✓	
38	STONE CHIP	S/N	\$ 180.00	✓	
39	METAL FILLER POWDER	S/N	\$ 280.00	✓	
40	SUNDRIES <i>new</i>		\$ 500.00	✓	25.44
TOTAL SPARE PARTS			\$ 19,800.00		
TOTAL LABOUR CHARGES			\$ 20,752.00		
GRAND TOTAL			\$ 40,552.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *30/03/23.*
AUTHORISED DATE :
EXCESS COST : *06 Days. Hs*
LIABILITY :
REMARKS : *are authorised, 05 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT