

(08/11/13) wsf

ASS. REC. BY: John

REF:

CS/LIP 2300 3353/Rqy3

0134

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF 5066Jat Workshop m/s SHU FATTof 1000, BUKIT MERAH LN 3 #01-90Insured: LIP

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 70K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMF 5066J Yr Regn: 2018 / No VType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Accent 1.4 CRT c.c. 1368Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 44022 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCU41BTKU431344Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / 8/Rim / STD A/Rim or

Tyre Size: F: _____ R: _____

175/10R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYOTA / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/03/23 D.O.I. 31/03/23Survey held at SHU FATTDes. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 47K

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS \$ _____

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____)



樹發汽車修理廠 SHU FATT AUTO WORKS



BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw/SF-quo

28th March 2023

TP-

SMF 5086 J HYUNDAI ACCENT

		S\$
Spare Parts	1 Left firt headlight. ?	360.00
	1 Frt bumper. de	320.00
	12 Frt bumper clips. @\$2.50	30.00
	21 Frt bumper side retainers. @\$10/- ? LH	20.00
	1 Left firt fender. Lt	200.00
	1 Left firt fender cowl. de	50.00
	10 Left firt fender cowl. clips. @\$2.50	25.00
	1 Left firt door. Lt	560.00
	1 Left firt door glass outer moulding. ?	25.00
	1 Left firt door pillar stickers. X	25.00
	1 Left rear door. Lt	1200.00
	1 Left rear door glass outer moulding. ?	30.00
	1 Left rear door pillar stickers. X	25.00
	2 Left hub caps. @\$90/- sur	180.00
	12 Rear bumper clips. @\$2.50	30.00
	2 Rear bumper side retainers. @\$15/- X	30.00

		3110.00
		Add 10% 311.00

		3421.00
Labour	To knock, straighten firt support panel, firt inner panel, firt lower panel, firt side panel, left firt wheel house, left firt door pillar, left door centre pillar, left rear fender, left rear arch panel, renew firt bumper, firt headlight, firt fender, firt door, rear door and assembly.	1200.00 1000
	To respray damaged parts.	1350.00 1000
	To remove left carpets, upholstery to facilitate repairs and assembly.	80.00 60
	To remove, replace left firt door, left rear door glasses, regulators, motors, handles, boards, rubbers, mouldings, checkers, hinges and assembly.	280.00 120

		6331.00
		=====

Hankook 175/70R14
KMHCU41BTKU431344
43925

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
Hp 90010068
8 days
H/S
31/03/23 @1110
Rey after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 013G

Vehicle Details

Vehicle No.: SMF5086J
Vehicle to be Exported: No
Intended Deregistration Date: 02 Apr 2023
Vehicle Make: HYUNDAI
Vehicle Model: ACCENT (RB) 1.4 CVT
Primary Colour: White
Manufacturing Year: 2018
Engine No.: G4LCJU993180
Chassis No.: KMHCU41BTKU431344
Maximum Power Output: 73.6 kW (98 bhp)
Open Market Value: \$8,247.00
Original Registration Date: 15 Nov 2018
First Registration Date: 15 Nov 2018
Transfer Count: 0
Actual ARF Paid: \$8,247.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Nov 2028
PARF Rebate Amount: \$6,185.00

Intended COE Rebate Details

COE Expiry Date: 14 Nov 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$28,457.00
COE Rebate Amount: \$15,983.00
Total Rebate Amount: \$22,168.00

Hyundai Accent 1.4A

Overview

Insurance

Financial

Accessories

Similar

Research

Photos

Price

\$69,888

Depreciation ⓘ

\$11,970 /yr

[View models with similar depre](#)

Reg Date

24-Sep-2018

(5yrs 5mths 21days COE left)

Mileage

42,000 km (9.3k /yr)

Manufactured ⓘ

2018

Road Tax ⓘ

\$608 /yr

Transmission

Auto

Dereg Value ⓘ

\$20,964 as of today ([change](#))

OMV ⓘ

\$8,503

COE ⓘ

\$26,608

ARF ⓘ

\$8,503

Engine Cap

1,368 cc

Power

73.6 kW (98 bhp)

Curb Weight ⓘ

1,115 kg

No. of Owners ⓘ

1

Type of Vehicle

[Mid-Sized Sedan](#)