

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

ALLIANZ INSURANCE SINGAPORE PTE LTD  
79 ROBINSON ROAD  
#09-01 SINGAPORE 068897

Ref: CS3/AIS23003355/y3

Date: 30/03/2023

Code: AIS

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

<b>Insured Veh.</b>	SML 5742S	<b>Veh. Inspected</b>	FBC 7438K
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	2023 32006532JK	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	SHANTI	<b>Assign Date</b>	30/03/2023

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

**4. Description of Damages**

--

**5. General Information**

<b>Accident Date</b>	24/03/2023	<b>Inspection Date</b>	
<b>Survey held at</b>	CHEK KONG MOTOR 387B YEW YEE INDUSTRIAL ESTATE WOODLANDS ROAD SINGAPORE 677948		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--