

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	ECICS LTD			Ref:	CS3/ICS23003359/y3	
	10 EUNOS ROAD SINGAPORE POS SINGAPORE 4086	T CENTRE #09-04A		Date:	31/03/2023	
				Code:	ICS	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLS 6863U	Veh. Inspected		SFB 5288Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	DMPC2300214H/ST	Excess (\$)		0.00	
	Assign From	SHARON TAN	Assign Date		30/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	28/03/2023	Inspection Dat	е		
	Survey held at	MONSTER GARAGE				
		1B KAKI BUKIT ROAD 3 EAST POINT TERRACE SINGAPORE 417822				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					