

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/III23003360/TWY3M4**Date:** 27/04/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447_02
<b>Claimant Vehicle No :</b>	SMG2554P	<b>Insured Vehicle No :</b>	SLN1937A
Date of Loss:	23/03/2023	Nature of Claim:	TP
		Claim No:	N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMG2554P</b>	Engine No:	2ZR0C35168
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800344687
Reg. Date:	12/12/2018 (Man. Year: 2018)	Odometer:	343102 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment:	30/03/2023		
Date Inspected:	20/04/2023	Inspected At:	Trident Auto Service Centre Pte Ltd (HQ) 8 Kaki bukit Ave 4, #02-42 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	0.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2023)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG2554P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >